

AUTOBAY PTE LTD

1 Kaki Bukit Avenue 6 #02-11 AutoBay @ Kaki Bukit Singapore 417883

Tel : 8618 6116 Fax : 6636 5355

UEN: 200909070G

Not Authorized

19/11/24

19 November 2024

Reg No.: GBM 2727 G
Model: TOYOTA HIACE

Repair sum 10,500

15 days

QTY	DESCRIPTION	AMT S\$
<u>List Items</u>		
1	Rear windscreen glass <i>shattered</i>	\$ 1,290.30 ✓
1	Rear windscreen moulding <i>NS</i>	\$ 130.50 X
1	Rear tailgate <i>body DD</i>	\$ 1,993.50 ✓
2	Rear tailgate dampers <i>11</i>	\$ 508.40 X
1	Rear tailgate inner trim board <i>De/Torn</i>	\$ 286.95 ✓
1	Rear tailgate inner center lock remote <i>Daye</i>	\$ 438.60 ✓
1	Rear tailgate lock cover <i>Dis</i>	\$ 58.00 ✓
1	Rear tailgate lock <i>Daye</i>	\$ 223.30 ✓
1	Rear tailgate lock catch <i>11</i>	\$ 65.90 X
1	Rear tailgate logo <i>new</i>	\$ 61.90 ✓
1	Rear tailgate outer garnish <i>Grand</i>	\$ 219.20 ✓
1	Rear tailgate rubber <i>twi</i>	\$ 328.48 ✓
1	Rear third brake lamp <i>11</i>	\$ 255.00 X
1	Rear wiper arm <i>11</i>	\$ 57.60 X
1	Rear wiper motor <i>11</i>	\$ 989.70 X
2	Rear taillamps <i>MS 5/20 0/5 11</i>	\$ 771.00 <i>12C</i>
1	Rear taillamp panel <i>MS Body DD</i>	\$ <i>385.50</i> 923.80 ✓
1	Rear taillamp lower garnish <i>MS Dis</i>	\$ <i>722.10</i> 230.00 ✓
1	Rear taillamp lower garnish side retainer <i>MS 0/5</i>	\$ <i>187.50</i> 76.80 ✓
1	Rear bumper <i>Dis</i>	\$ 695.20 ✓
2	Rear bumper brackets <i>Buf</i>	\$ 57.20 ✓
1	Rear bumper side retainer <i>MS 0/5</i>	\$ 132.40 ✓
1	Rear bumper step panel <i>Buf</i>	\$ 285.00 ✓
1	Rear end panel <i>Body DD</i>	\$ <i>616.20</i> 887.90 ✓
1	Rear end panel top moulding <i>NZ</i>	\$ 108.60 X
2	Rear number plate lamps <i>11</i>	\$ 164.00 X
1	Rear floor panel <i>R</i>	\$ 1,880.80 X
1	Rear side body panel -LH <i>Body DD</i>	\$ 1,765.50 ✓
1	Rear side panel inner board <i>11</i>	\$ 338.70 X
1	Rear side panel air vent <i>MS Dis</i>	\$ 100.40 ✓
		\$ 15,324.63
Less 25%		\$ 3,831.16
		\$ 11,493.47

Special Nett Items

1	Rear windscreen sealant	\$	Net	80.00	40
1	Rear view camera	\$	Net	600.00	X
1	Rear tailgate "70KM/H" sticker	\$	Net	28.00	10
1	Rear wiper blade	\$	Net	45.00	X
1	Rear bumper clip (1 set)	\$	Net	60.00	30
1	Rear number plate	\$	Net	50.00	40
1	Rear reverse camera	\$	Net	450.00	X
1	Rear floor aluminium board	\$	Net	3,000.00	300
				\$	4,313.00

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$	Net	120.00	X
3	To remove and refit rear reverse camera.	\$		150.00	30
4	To transfer rear tailgate mechanism and wiring assembly.	\$		80.00	50
5	To remove and refit rear windscreen glass.	\$		180.00	120
6	To apply undercoating.	\$		200.00	90
7	Panel beating.	\$		2,000.00	1500
8	To re-spray painting on the affected areas.	\$		2,100.00	1000
				\$	4,910.00

Grand Total :

\$ 20,716.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-991803
252
1-743843
S.N-1420
2-2820
1167853
1000