

(08/11/13) wef

A.S. REC. BY: Marcus

REF:

CS/18/24/10367/Uq3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: G3M 27276

at Workshop m/s: Ants bay

of _____

Insured: G3L 19325

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$ 83k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C404C

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 844 907

Veh No: G3M 27276 Yr Regn: 27/10/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / 2.0 DX

Make: Toyota hiace c.c. 1998

Colour: M-A A/C: Insured / Std / NI / NA

Sp. Reading: 5-9109 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-215

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/1/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

00p 10500

note new parts replacement

Repair sum \$10500 in hand Victor Med \$10216.47, 492)

Date/Time, File Pass to?

1) 14/2 trip: ☐ : Preli. ReportDate/Time, File Return to? ☐ : Final Report

2) _____

Days Of Repair: 15

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) MER-TP 10500

AUTOBAY PTE LTD

1 Kaki Bukit Avenue 6 #02-11 AutoBay @ Kaki Bukit Singapore 417883

Tel : 8618 6116 Fax : 6636 5355

UEN: 200909070G

Not Authorized

19/11/24

19 November 2024

Reg No.: GBM 2727 G
Model: TOYOTA HIACE

Repair sum 10,500
15 days

QTY	DESCRIPTION	AMT S\$
<u>List Items</u>		
1	Rear windscreen glass <i>shattered</i>	\$ 1,290.30 ✓
1	Rear windscreen moulding <i>NS</i>	\$ 130.50 X
1	Rear tailgate <i>body DD</i>	\$ 1,993.50 ✓
2	Rear tailgate dampers <i>11</i>	\$ 508.40 X
1	Rear tailgate inner trim board <i>Del/Torn</i>	\$ 286.95 ✓
1	Rear tailgate inner center lock remote <i>Daye</i>	\$ 438.60 ✓
1	Rear tailgate lock cover <i>Dis</i>	\$ 58.00 ✓
1	Rear tailgate lock <i>Daye</i>	\$ 223.30 ✓
1	Rear tailgate lock catch <i>11</i>	\$ 65.90 X
1	Rear tailgate logo <i>new</i>	\$ 61.90 ✓
1	Rear tailgate outer garnish <i>Grand</i>	\$ 219.20 ✓
1	Rear tailgate rubber <i>new</i>	\$ 328.48 ✓
1	Rear third brake lamp <i>11</i>	\$ 255.00 X
1	Rear wiper arm <i>11</i>	\$ 57.60 X
1	Rear wiper motor <i>11</i>	\$ 989.70 X
2	Rear taillamps <i>MS 320 0/5 11</i>	\$ 771.00 <i>12C</i>
1	Rear taillamp panel <i>MS Body DD</i>	\$ <i>385.50</i> 923.80 ✓
1	Rear taillamp lower garnish <i>MS Dis</i>	\$ <i>722.10</i> 230.00 ✓
1	Rear taillamp lower garnish side retainer <i>MS 010</i>	\$ <i>187.50</i> 76.80 ✓
1	Rear bumper <i>Dis</i>	\$ 695.20 ✓
2	Rear bumper brackets <i>Buf</i>	\$ 57.20 ✓
1	Rear bumper side retainer <i>MS 010</i>	\$ 132.40 ✓
1	Rear bumper step panel <i>Buf</i>	\$ 285.00 ✓
1	Rear end panel <i>Body DD</i>	\$ <i>616.20</i> 887.90 ✓
1	Rear end panel top moulding <i>NZ</i>	\$ 108.60 X
2	Rear number plate lamps <i>11</i>	\$ 164.00 X
1	Rear floor panel <i>12</i>	\$ 1,880.80 X
1	Rear side body panel -LH <i>Body DD</i>	\$ 1,765.50 ✓
1	Rear side panel inner board <i>11</i>	\$ 338.70 X
1	Rear side panel air vent <i>MS Dis</i>	\$ 100.40 ✓
		\$ 15,324.63
Less 25%		\$ 3,831.16
		\$ 11,493.47

Special Nett Items

1	Rear windscreen sealant	\$	Net	80.00	40
1	Rear view camera	\$	SC	600.00	X
1	Rear tailgate "70KM/H" sticker	\$	Net	28.00	10
1	Rear wiper blade	\$	Net	45.00	X
1	Rear bumper clip (1 set)	\$	Net	60.00	30
1	Rear number plate	\$	Bent	50.00	40
1	Rear reverse camera	\$	SC	450.00	X
1	Rear floor aluminium board	DDJ \$	Bent	3,000.00	300
		\$		4,313.00	

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$	Net	120.00	X
3	To remove and refit rear reverse camera.	\$		150.00	30
4	To transfer rear tailgate mechanism and wiring assembly.	\$		80.00	50
5	To remove and refit rear windscreen glass.	\$		180.00	120
6	To apply undercoating.	\$		200.00	90
7	Panel beating.	\$		2,000.00	1500
8	To re-spray painting on the affected areas.	\$		2,100.00	1000
		\$		4,910.00	

Grand Total :

\$ 20,716.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-991803
252
P-743843
S.N-1420
2-2820
1167853
10000

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	404C
Vehicle Details	
Vehicle No.:	GBM2727G
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 2.0 DX AUTO
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	1TR2385209
Chassis No.:	TRH2005048665
Maximum Power Output:	-
Open Market Value:	\$27,637.00
Original Registration Date:	27 Oct 2022
First Registration Date:	27 Oct 2022
Transfer Count:	0
Actual ARF Paid:	\$1,382.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2032
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$56,610.00
COE Rebate Amount:	\$44,907.00
Total Rebate Amount:	\$44,907.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 20 Nov 2024

OK

PREMIUM AD



Toyota Hiace 2.0A

\$76,777

Instl. \$1,011 /mth

\$10,430 /yr

30-Mar-2022

(7yrs 4mths COE left)

56,000 km

1,998 cc

1 Owner



Almost brand new condition in original paintwork! Powerful and reliable, ultra comfy workhorse for both business and personal usage! 100% loan and high trade in available, call for a non obligation test drive and viewing today!

Posted 18-Nov-2024

☐ Compare

PREMIUM AD



★ StarAd View All

Carens Diesel 1.7a At \$44,800. 1 Owner Only.

Lowest Price In The Market, Please Feel Free To View As Owner Changing... Boss Motoring

HIN LUNG AUTO PTE LTD

One Stop Car Hub

Finance, Insurance, Workshop New and Used Cars

Since 1983



Toyota Hiace 2.0A DX

\$85,988

Instl. \$1,133 /mth

\$10,970 /yr

21-Sep-2022

(7yrs 10mths COE left)

N.Air

1,998 cc

1 Owner



Bid number plate. 1 owner with almost new condition. Original condition and very well maintained with very healthy smooth engine and gearbox. Enjoy lifetime servicing and unlimited mileage warranty. Trade-in are welcome, bank loan welcome. Contact us to viewing this unit now!

ABS Bus Pte Ltd|Posted 16-Nov-2024

☐ Compare

PREMIUM AD



Toyota Hiace 2.0A DX

\$79,800

Instl. \$1,051 /mth

\$11,050 /yr

10-Feb-2022

(7yrs 2mths COE left)

N.Air

1,998 cc

2 Owners



One Owner Only! Low Mileage! Auto Transmission! Class 3A Can Drive! All Original Condition! Accident Free! Extremely Durable And Extremely Low On Maintenance Cost! No Need Repair Needed. Still Under Warranty! High Loan Available! Trade In Welcome! Call Us Now!

Net Link Partners Pte Ltd|Posted 16-Nov-2024

☐ Compare

PREMIUM AD



Toyota Hiace 2.0A

\$89,800

Instl. \$1,183 /mth

\$11,850 /yr

17-Jun-2022

(7yrs 6mths COE left)

N.Air

1,998 cc

1 Owner



Best deal Toyota Hiace MINI bus! Auto transmission! No gimmick! Real unit! Still under warranty! Comes with LED headlight and rear aircon! Can be convert to G plate! Well maintained by the owner. Accident free! Extremely durable and extremely low on maintenance cost! No need repair needed. Trade in are welcome! We provide high loan with low interest rates! Call us for viewing and test drive now.

Net Link Partners Pte Ltd|Posted 14-Nov-2024

☐ Compare

PREMIUM AD

Compare