



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110370/Uvh3m4
75 BRAS BASAH ROAD	Date:	27/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMN 3589X	Veh. Inspected	GBL 928L
Policy No.	-	Coverage	0
Claim No.	MT/1291647-001	Excess	\$0.00
Assign From	AZHARI AFIDI	Assign Date	19/11/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE DX 2.8 AUTO	C.C	2754
Engine No.	1GD8686783	Year of Reg.	18/03/2021
Chassis No.	GDH2011055356	Colour	SILVER
Odometer	158819 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	BLACKHAWK	6
L/H Front Tyre	195R15	BLACKHAWK	6
R/H Rear Tyre	195R15	BLACKHAWK	6
L/H Rear Tyre	195R15	BLACKHAWK	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2024	Inspection Date	19/11/2024 (11:05)
Survey held at	CARSMITH PTE LTD - 8 KAKI BUKIT AVE 4, #04-35, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days