



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110373/Evp3m4
16 RAFFLES QUAY	Date:	17/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1912B	Veh. Inspected	SLK 409E
Policy No.	-	Coverage	0
Claim No.	D24010117MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	18/11/2024

### 2. Vehicle Details

Make & Model	BMW IX3	C.C	-
Engine No.	-	Year of Reg.	23/11/2023
Chassis No.	WBY42DU060SC04577	Colour	BLACK
Odometer	25814 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45R20	BRIDGESTONE	6
L/H Front Tyre	245/45R20	BRIDGESTONE	6
R/H Rear Tyre	245/45R20	BRIDGESTONE	6
L/H Rear Tyre	245/45R20	BRIDGESTONE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	17/11/2024	Inspection Date	20/11/2024
Survey held at	TRANS EUROKARS PTE LTD - 27A TANJONG PENJURU, SINGAPORE 609042		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days