



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP INC
Xiao Chen.

OOI PENG HONG
BLK 211 BOON LAY PLACE #16-135
SINGAPORE 640211

TAX INVOICE

Repair Code : CLM18461

Date in : 18/11/2024

Vehicle Num. : SKP3664A

Model : MERCEDES BENZ C180K

Chassis/Eng# : WDD2040452A511756/27191031343250

Contact : 97742689

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	1806.00	✓ 1,806.00
FRONT RH DOOR CHROME MOULDING <i>new</i>	1	186.00	✓ 186.00
FRONT RH DOOR WEATHER STRIP <i>new</i>	1	225.00	✓ 225.00
FRONT RH FENDER 'BLUE EFFICIENCY' EMBLEM <i>new</i>	1	80.00	✓ 80.00
FRONT RH FENDER (ALUMINIUM) <i>Dented</i>	1	920.00	✓ 920.00
FRONT RH FENDER CHROME MOULDING <i>new</i>	1	92.00	✓ 92.00
FRONT RH FENDER INNER SHIELD (REAR) <i>new</i>	1	145.00	x 145.00
FRONT RH KNUCKLE ARM <i>new</i>	1	796.00	x 796.00
FRONT RH KNUCKLE ARM BEARING <i>new</i>	1	525.00	x 525.00
FRONT RH LOWER ARM <i>new</i>	1	625.00	x 625.00
FRONT RH SPORT RIM <i>cut</i>	1	980.00	600/sal ✓ 980.00
ROCKER GARNISH RH <i>new</i>	1	526.00	x 526.00
Subtotal before discount			6,906.00
Percentage discount 10%			690.60
Sub-total 1			6,215.40
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	50.00 x
ROCKER GARNISH RH CLIPS - SET <i>new</i>	1	60.00	60.00 x

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

OOI PENG HONG
 BLK 211 BOON LAY PLACE #16-135
 SINGAPORE 640211

Contact : 97742689

TAX INVOICE

Repair Code : CLM18461
 Date in : 18/11/2024
 Vehicle Num. : SKP3664A
 Model : MERCEDES BENZ C180K
 Chassis/Eng# : WDD2040452A511756/27191031343250

Subtotal before discount	110.00
Percentage discount 0%	0.00
Sub-total 2	110.00
Parts-total	6,325.40

LABOUR

To reset system after repair works	X 400.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	X 300.00
To road test driving, check and resetting wheel alignments system.	80 100.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	60 80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1220 600 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	400 800.00
To apply anti-rust chemical on repaired and replaced panel.	80 120.00
Labour Total	2,800.00
Parts & Labour Total	9,125.40

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultancy hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

page 2

Adrian L
 L/S 19/11/24.

total: 4758.10

L/S: 3.8K ✓
 09/11/24