



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110376/Enh3m4
75 BRAS BASAH ROAD	Date:	05/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 1003T	Veh. Inspected	SNN 5952E
Policy No.	-	Coverage	0
Claim No.	MT/1305088-001	Excess	\$0.00
Assign From	SHAFAWATI	Assign Date	19/11/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS	C.C	1798
Engine No.	2ZRZ097037	Year of Reg.	18/12/2023
Chassis No.	MR2BZ3BE800013550	Colour	WHITE
Odometer	66225 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45R17	MICHELIN	5
L/H Front Tyre	225/45R17	MICHELIN	5
R/H Rear Tyre	225/45R17	MICHELIN	5
L/H Rear Tyre	225/45R17	MICHELIN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/10/2024	Inspection Date	19/11/2024 (11:43)
Survey held at	8 KAKI BUKIT AVENUE 4 #08-19 PREMIER @ KAKI BUKIT SINGAPORE 415875 - REPAIRER: MIRAI AUTO PERFORMANCE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days