

ASS. REC. BY:

REF:

MSG

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

EM

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

892K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNL 86597

Yr Regn: 05.18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MC C/A 200

c.c. 1595

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

102883

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDC 1589432J 469785

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

R:

235/45R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

20/6/24

D.O.I.

28/6/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA &amp; EM not ready

3/7 67Rup @ 67501: Car W

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                          |                                  |
|------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                         |                                  |
| Owner ID Type:                                                                                                                           | Singapore NRIC                   |
| Owner ID:                                                                                                                                | 611G                             |
| <b>Vehicle Details</b>                                                                                                                   |                                  |
| Vehicle No.:                                                                                                                             | SNL8659T                         |
| Vehicle to be Exported:                                                                                                                  | No                               |
| Intended Deregistration Date:                                                                                                            | 28 Jun 2024                      |
| Vehicle Make:                                                                                                                            | MERCEDES BENZ                    |
| Vehicle Model:                                                                                                                           | GLA200 AMG AUTO                  |
| Primary Colour:                                                                                                                          | Black                            |
| Manufacturing Year:                                                                                                                      | 2017                             |
| Engine No.:                                                                                                                              | 27091031524693                   |
| Chassis No.:                                                                                                                             | WDC1569432J469785                |
| Maximum Power Output:                                                                                                                    | 115.0 kW (154 bhp)               |
| Open Market Value:                                                                                                                       | \$34,997.00                      |
| Original Registration Date:                                                                                                              | 14 May 2018                      |
| First Registration Date:                                                                                                                 | 14 May 2018                      |
| Transfer Count:                                                                                                                          | 1                                |
| Actual ARF Paid:                                                                                                                         | \$40,996.00                      |
| <b>Intended PARF Rebate Details</b>                                                                                                      |                                  |
| PARF Eligibility:                                                                                                                        | Yes                              |
| PARF Eligibility Expiry Date:                                                                                                            | 13 May 2028                      |
| PARF Rebate Amount:                                                                                                                      | \$26,647.00                      |
| <b>Intended COE Rebate Details</b>                                                                                                       |                                  |
| COE Expiry Date:                                                                                                                         | 13 May 2028                      |
| COE Category:                                                                                                                            | E - Open - all except motorcycle |
| COE Period(Years):                                                                                                                       | 10                               |
| QP Paid:                                                                                                                                 | \$39,000.00                      |
| COE Rebate Amount:                                                                                                                       | \$15,107.00                      |
| <b>Total Rebate Amount:</b>                                                                                                              | <b>\$41,754.00</b>               |
| <b>Message</b>                                                                                                                           |                                  |
| You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE. |                                  |

The information contained herein is correct as at 27 Jun 2024

OK

R039150  
28.6.24 12:42  
SNL8659T  
EM



Mercedes-Benz : 156 (GLA Class)  
4-Wheel Total Alignment

Front : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -1°24' | -1°24' | -1°10' -0°31'   |
| 6°04'  | 6°04'  |                 |
| 0°05'  | 0°05'  | 0°02' 0°12'     |
| 10°00' | 10°00' |                 |
| 8°36'  | 8°36'  |                 |
|        |        | -1°24' -0°24'   |

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -1°00' | -1°00' | -1°10' -0°31'   |
| 5°50'  | 5°50'  |                 |
| 0°17'  | 0°17'  | 0°02' 0°12'     |
| 9°51'  | 9°51'  |                 |
| 8°51'  | 8°51'  |                 |
|        |        | -1°24' -0°24'   |

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°24' | -0°24' | -0°24' 0°24'    |
| 0°14'  | 0°14'  | -0°30' 0°30'    |
| 0°09'  | 0°09'  |                 |
| 0°22'  | 0°22'  | 0°03' 0°24'     |

Rear : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -1°03' | -1°03' |                 |
| 0°09'  | 0°09'  | -0°06' 0°08'    |

Camber  
Toe

Rear : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -2°34' | -2°34' |                 |
| -0°53' | -0°53' | -0°06' 0°08'    |

Rear

Cross Camber  
Total Toe  
Thrust Angle

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| 1°31'  | 1°31'  | -0°30' 0°30'    |
| -0°44' | -0°44' | -0°05' 0°09'    |
| 0°31'  | 0°31'  | -0°08' 0°08'    |



# E M Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity  
Singapore 575722  
Tel: 64560226

GST/Reg. No: 201016308K

*Not Notified*

*1/1/24*

*Resurvey After Claim*

*5 days*

## ESTIMATE

Date : 27th June 2024

Mr **Teo Buck Seng**  
Blk 431B Northshore Drive #21-800  
Singapore 822431

Veh No : **SNL 8659T**  
Make/Model : **Mercedes GLA200**  
Chassis No : WDC1569432J469785  
Date of Acc : 26.06.24  
TP Veh No : SNC 4688H

| S/No             | Qty  | Description                                 | Unit Price | Amount |
|------------------|------|---------------------------------------------|------------|--------|
| <b>Materials</b> |      |                                             |            |        |
| 1                | 1 pc | Frt Door RH <i>RM ✓</i>                     |            |        |
| 2                | 1 pc | Frt Door Weatherstrip RH <i>506.00 - RM</i> |            |        |
| 3                | 1 pc | Rear Door RH <i>nd/way ✓</i>                |            |        |
| 4                | 1 pc | Rear Door Weatherstrip RH <i>RM 506.00</i>  |            |        |
| 5                | 1 pc | Rear Wheel Arch Protector RH <i>RM</i>      |            |        |
| 6                | 1 pc | Rear Bumper <i>RM X</i>                     |            |        |
| 7                | 1 pc | PDC Sensor RH <i>RM X</i>                   |            |        |
| 8                | 1 pc | Skirt Rocker Chrome Skirting RH <i>RM X</i> |            |        |
| 9                | 1 pc | Rear Sport Rim RH <i>nd -</i>               |            |        |
| 10               | 1 pc | Rear Wheel Bearing RH <i>?</i>              |            |        |
| 11               | 1 PC | Rear Shock Absorber RH <i>?</i>             |            |        |
| 12               | 1 pc | Rear Lower Arm RH <i>?</i>                  |            |        |
| 13               | 1 pc | Rear Knuckle Arm RH <i>?</i>                |            |        |

Less 10% : \$ -  
Parts Total : \$ -

|                     |       |                           |
|---------------------|-------|---------------------------|
| <b>Special Nett</b> |       |                           |
| 1                   | 1 pc  | Frt Door Inner Sealer RH  |
| 2                   | 1 pc  | Rear Door Inner Sealer RH |
| 3                   | 1 set | Rear Bumper Clips         |

\$ *RM* 80.00 X  
\$ *RM* 80.00 X  
\$ *RM* 60.00 X  
Special Nett : \$ 220.00

|               |                                                                                                       |
|---------------|-------------------------------------------------------------------------------------------------------|
| <b>Labour</b> |                                                                                                       |
| 1             | To remove & rearrange electrical wirings, check lightings                                             |
| 2             | To remove & transfer front door components.                                                           |
| 3             | To remove & transfer rear door components.                                                            |
| 4             | To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident. |
| 5             | To remove, replace rear undercarriage parts                                                           |
| 6             | To remove, instal reverse sensor                                                                      |
| 7             | To reset wheel alignment                                                                              |
| 8             | Putty and respray painting on affected portions.                                                      |
| 9             | To remove & renew PDC sensor                                                                          |
| 10            | Rust proofing on affected portions.                                                                   |

\$ 80.00 *2d*  
\$ 150.00 *60h*  
\$ 150.00 *60h*  
\$ 1,000.00 *40d*  
\$ 350.00 *?*  
\$ *RM* 100.00 *X*  
\$ 100.00 *60h*  
\$ 1,000.00 *66d*  
\$ *RM* 100.00 *X*  
\$ *RM* 120.00 *X*

Labour Total : \$ 3,150.00

for E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Parts & Labour :

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

Acknowledged by Repairer

Signature:

Date:

# EM Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity  
Singapore 575722  
Tel: 64560226  
GST/Reg. No: 201016308K

Not Authorised  
L1 Rep & 6780h  
Penny After Pain

## ESTIMATE

Date : 27th June 2024

Mr **Teo Buck Seng**  
Blk 431B Northshore Drive #21-800  
Singapore 822431

Veh No : **SNL 8659T**  
Make/Model : **Mercedes GLA200**  
Chassis No : **WDC1569432J469785**  
Date of Acc : **26.06.24**  
TP Veh No : **SNC 4688H**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

| S/No                | Qty   | Description                                                                                           | Unit Price             | Amount         |
|---------------------|-------|-------------------------------------------------------------------------------------------------------|------------------------|----------------|
| <b>Materials</b>    |       |                                                                                                       |                        |                |
| 1                   | 1 pc  | Frt Door RH                                                                                           | 164.895m               | \$ 2,176.46 ✓  |
| 2                   | 1 pc  | Frt Door Weatherstrip RH                                                                              | na                     | \$ 329.78 502m |
| 3                   | 1 pc  | Rear Door RH                                                                                          | Ref/Way                | \$ 2,344.87 ✓  |
| 4                   | 1 pc  | Rear Door Weatherstrip RH                                                                             | 164.895m               | \$ 329.78 502m |
| 5                   | 1 pc  | Rear Wheel Arch Protector RH                                                                          | na                     | \$ 270.76 ✓    |
| 6                   | 1 pc  | Rear Bumper                                                                                           | na                     | \$ 1,804.33 X  |
| 7                   | 1 pc  | PDC Sensor RH                                                                                         | na                     | \$ 298.00 X    |
| 8                   | 1 pc  | Skirt Rocker Chrome Skirting RH                                                                       | na                     | \$ 1,508.00 X  |
| 9                   | 1 pc  | Rear Sport Rim RH                                                                                     | 1205                   | \$ 1,633.61 ✓  |
| 10                  | 1 pc  | Rear Wheel Bearing RH                                                                                 | 344                    | \$ 407.76 ✓    |
| 11                  | 1 PC  | Rear Shock Absorber RH                                                                                | na                     | \$ 632.00 X    |
| 12                  | 1 pc  | Rear Lower Arm RH                                                                                     | na                     | \$ 504.00 X    |
| 13                  | 1 pc  | Rear Knuckle Arm RH                                                                                   | 1200                   | \$ 1,292.00 ✓  |
|                     |       |                                                                                                       |                        | \$ 13,531.35   |
|                     |       |                                                                                                       | Less 10%               | \$ 1,353.14    |
|                     |       |                                                                                                       | Parts Total :          | \$ 12,178.22   |
| <b>Special Nett</b> |       |                                                                                                       |                        |                |
| 1                   | 1 pc  | Frt Door Inner Sealer RH                                                                              | na                     | \$ 80.00 X     |
| 2                   | 1 pc  | Rear Door Inner Sealer RH                                                                             | na                     | \$ 80.00 X     |
| 3                   | 1 set | Rear Bumper Clips                                                                                     | na                     | \$ 60.00 X     |
|                     |       |                                                                                                       | Special Nett :         | \$ 220.00      |
| <b>Labour</b>       |       |                                                                                                       |                        |                |
| 1                   |       | To remove & rearrange electrical wirings, check lightings                                             | \$                     | 80.00 20h      |
| 2                   |       | To remove & transfer front door components.                                                           | \$                     | 150.00 60h     |
| 3                   |       | To remove & transfer rear door components.                                                            | \$                     | 150.00 60h     |
| 4                   |       | To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident. | \$                     | 1,000.00 4.50h |
| 5                   |       | To remove, replace rear undercarriage parts                                                           | \$                     | 350.00 60h     |
| 6                   |       | To remove, instal reverse sensor                                                                      | \$na                   | 100.00 X       |
| 7                   |       | To reset wheel alignment                                                                              | \$                     | 100.00 60h     |
| 8                   |       | Putty and respray painting on affected portions.                                                      | \$                     | 1,000.00 6.50h |
| 9                   |       | To remove & renew PDC sensor                                                                          | \$na                   | 100.00 X       |
| 10                  |       | Rust proofing on affected portions.                                                                   | \$na                   | 120.00 X       |
|                     |       |                                                                                                       | Labour Total :         | \$ 3,150.00    |
|                     |       |                                                                                                       | Total Parts & Labour : | \$ 15,548.22   |

for EM Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.