

E M Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity
Singapore 575722
Tel: 64560226
GST/Reg. No: 201016308K

Not Authorised
L1 Lp @ 6700h
Punery After Pain

ESTIMATE

Date : 27th June 2024

Mr **Teo Buck Seng**
Blk 431B Northshore Drive #21-800
Singapore 822431

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Veh No : **SNL 8659T**

Make/Model : **Mercedes GLA200**

Chassis No : **WDC1569432J469785**

Date of Acc : **26.06.24**

TP Veh No : **SNC 4688H**

Acknowledged by Repairer

S/No	Qty	Description	Unit Price	Amount
------	-----	-------------	------------	--------

Materials

1	1 pc	Frt Door RH	164.895m	\$ 2,176.46 ✓
2	1 pc	Frt Door Weatherstrip RH	na	\$ 329.78 502m
3	1 pc	Rear Door RH	2274.37	\$ 2,344.87 ✓
4	1 pc	Rear Door Weatherstrip RH	164.895m	\$ 329.78 502m
5	1 pc	Rear Wheel Arch Protector RH	na	\$ 270.76 ✓
6	1 pc	Rear Bumper	na	\$ 1,804.33 X
7	1 pc	PDC Sensor RH	na	\$ 298.00 X
8	1 pc	Skirt Rocker Chrome Skirting RH	na	\$ 1,508.00 X
9	1 pc	Rear Sport Rim RH	1205	\$ 1,633.61 ✓
10	1 pc	Rear Wheel Bearing RH	344	\$ 407.76 ✓
11	1 PC	Rear Shock Absorber RH	na	\$ 632.00 X
12	1 pc	Rear Lower Arm RH	na	\$ 504.00 X
13	1 pc	Rear Knuckle Arm RH	1200	\$ 1,292.00 ✓
				\$ 13,531.35
Less 10%				\$ 1,353.14
Parts Total :				\$ 12,178.22

Special Nett

1	1 pc	Frt Door Inner Sealer RH	na	\$ 80.00 X
2	1 pc	Rear Door Inner Sealer RH	na	\$ 80.00 X
3	1 set	Rear Bumper Clips	na	\$ 60.00 X
Special Nett :				\$ 220.00

Labour

1	To remove & rearrange electrical wirings, check lightings	\$ 80.00 20h
2	To remove & transfer front door components.	\$ 150.00 60l
3	To remove & transfer rear door components.	\$ 150.00 60l
4	To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$ 1,000.00 450l
5	To remove, replace rear undercarriage parts	\$ 350.00 60l
6	To remove, instal reverse sensor	\$ 100.00 X
7	To reset wheel alignment	\$ 100.00 60l
8	Putty and respray painting on affected portions.	\$ 1,000.00 660l
9	To remove & renew PDC sensor	\$ 100.00 X
10	Rust proofing on affected portions.	\$ 120.00 X
Labour Total :		\$ 3,150.00

Total Parts & Labour : \$ 15,548.22

for E M Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.