

EM Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity
Singapore 575722
Tel: 64560226
GST/Reg. No: 201016308K

Not Authorized
L1 Reg & 6750h
Running After Pain

ESTIMATE

Mr **Teo Buck Seng**
Blk 431B Northshore Drive #21-800
Singapore 822431

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date : 27th June 2024

Veh No : SNL 8659T

Make/Model : Mercedes GLA200

Chassis No : WDC1569432J469785

Date of Acc : 26.06.24

TP Veh No : SNC 4688H

Acknowledged by Repairer

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Door RH	164.8PSN \$ 2,176.46	✓
2	1 pc	Frt Door Weatherstrip RH	\$ 329.78	50% ✓
3	1 pc	Rear Door RH	2274.37 \$ 2,344.87	✓
4	1 pc	Rear Door Weatherstrip RH	164.8PSN \$ 329.78	50% ✓
5	1 pc	Rear Wheel Arch Protector RH	GM \$ 270.76	✓
6	1 pc	Rear Bumper	SL \$ 1,804.33	X
7	1 pc	PDC Sensor RH	SL \$ 298.00	X
8	1 pc	Skirt Rocker Chrome Skirting RH	SL \$ 1,508.00	X
9	1 pc	Rear Sport Rim RH	1205 \$ 1,633.61	✓
10	1 pc	Rear Wheel Bearing RH	344 \$ 407.76	✓
11	1 PC	Rear Shock Absorber RH	\$ SL 632.00	X
12	1 pc	Rear Lower Arm RH	\$ SL 504.00	X
13	1 pc	Rear Knuckle Arm RH	1200 \$ 1,292.00	✓
			\$ 13,531.35	
			Less 10%	\$ 1,353.14
			Parts Total :	\$ 12,178.22
Special Nett				
1	1 pc	Frt Door Inner Sealer RH	NN \$ 80.00	X
2	1 pc	Rear Door Inner Sealer RH	NN \$ 80.00	X
3	1 set	Rear Bumper Clips	NN \$ 60.00	X
			Special Nett :	\$ 220.00
Labour				
1		To remove & rearrange electrical wirings, check lightings	\$ 80.00	20% ✓
2		To remove & transfer front door components.	\$ 150.00	60% ✓
3		To remove & transfer rear door components.	\$ 150.00	60% ✓
4		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$ 1,000.00	45% ✓
5		To remove, replace rear undercarriage parts	\$ 350.00	60% ✓
6		To remove, instal reverse sensor	\$ 100.00	X
7		To reset wheel alignment	\$ 100.00	60% ✓
8		Putty and respray painting on affected portions.	\$ 1,000.00	65% ✓
9		To remove & renew PDC sensor	\$ 100.00	X
10		Rust proofing on affected portions.	\$ 120.00	X
			Labour Total :	\$ 3,150.00
			Total Parts & Labour :	\$ 15,548.22



for EM Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.