



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110381/Uqh3e2
75 BRAS BASAH ROAD	Date:	26/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 1503T	Veh. Inspected	SMR 9037L
Policy No.	-	Coverage	0
Claim No.	MT/1304733-002	Excess	\$0.00
Assign From	CHARLOTTE CHEW	Assign Date	19/11/2024

2. Vehicle Details

Make & Model	TOYOTA SIENTA HYBRID (A)	C.C	1496
Engine No.	1NZR787558	Year of Reg.	30/01/2020
Chassis No.	NHP1707174092	Colour	BLACK
Odometer	344671 KM	Steering	DAMAGED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	GITI	6
L/H Front Tyre	185/60R15	GITI	6
R/H Rear Tyre	185/60R15	GITI	6
L/H Rear Tyre	185/60R15	GITI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/11/2024	Inspection Date	19/11/2024 (22:10)
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a.	Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	

5b.	Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days	