



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorized
in
merang

20 November 2024

REG NO.: PC 7113 G
MAKE/MODEL: TOYOTA HIACE

19/11/24

2/5 @ 7000

8 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

make phone call

QTY	DESCRIPTION	AMT(S\$)
LIST ITEMS		
1	Rear windscreen moulding	\$ NS 120.80 X
1	Rear tailgate	\$ Body 2,362.00 ✓
2	Rear tailgate dampers	\$ 17 694.20 X
1	Rear tailgate inner trim board	\$ 17 450.00 X
1	Rear tailgate lock	\$ 17 450.00 X
1	Rear tailgate logo	\$ 200 80.50 ✓
1	Rear tailgate rubber	\$ 17 379.80 ✓
1	Rear taillamp -LH	\$ 200 425.00 ✓
1	Rear taillamp lower garnish	\$ 200 284.20 ✓
1	Rear end panel	\$ 566.10 20/200 869.10 ✓
1	Rear end panel inner garnish	\$ 17 190.62 ✓
1	Rear taillamp panel LH	\$ 200 624.50 ✓
1	Rear keyless sensor	\$ 200 210.00 ✓
1	Rear bumper	\$ 735.20 200 938.00 ✓
1	Rear bumper top bracket	\$ 17 65.00 X
1	Rear bumper side retainer LH	\$ 200 112.40 ✓
1	Rear floor panel	\$ R 1,880.80 X
1	Rear side panel -LH	\$ 300 2,079.70 ✓
1	Rear side panel air vent LH	\$ 200 98.00 ✓
		\$ 12,314.62
	Less 25%	\$ 3,078.66
		\$ 9,235.97

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$ 200 80.00 40
1	Rear tailgate "70KM/H" sticker	\$ 200 25.00 10
1	Rear bumper clip (1 set)	\$ 200 50.00 30
1	Rear side panel sealant	\$ 200 120.00 50
		\$ 275.00

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes seat upholstery	\$ 180.00 100
3	To remove and refit rear windscreen glass.	\$ 180.00 120
4	To remove and refit quarter glass to assist repair.	\$ 150.00 100
5	To apply undercoating.	\$ 200.00 80
6	Panel beating.	\$ 1,800.00 1200
7	To re-spray painting on the affected areas.	\$ 1,600.00 900
		\$ 4,190.00

the Repairer of the following:

- To resurvey before/after spray painting
- To remove and refit part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal Page 1 of 1 is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 13,700.97

P- 8148.02
25.2
6111.02
130
2520