

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	587C
Vehicle Details	
Vehicle No.:	PC7113G
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1GD8262972
Chassis No.:	GDH2232000153
Maximum Power Output:	-
Open Market Value:	\$43,913.00
Original Registration Date:	23 May 2018
First Registration Date:	23 May 2018
Transfer Count:	1
Actual ARF Paid:	\$2,196.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$33,190.00
COE Rebate Amount:	\$11,744.00
Total Rebate Amount:	\$11,744.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 19 Nov 2024

OK



Toyota Hiace Commuter
3.0A High Roof

\$88,800 \$22,350 /yr 09-Nov-2018
(3yrs 11mths COE left) N.A.
Instl. \$1,956 /mth 2,982 cc 1 Owner Diesel

1 owner consignment unit! By appointment viewing only.

Net Link Partners Pte Ltd | Posted 11-Nov-2024

☐ Compare



Toyota Hiace
Commuter 3.0A

\$66,200 \$18,450 /yr 22-Jun-2018
(3yrs 7mths COE left) N.A. 2,982 cc
Instl. \$1,581 /mth 5 Owners Diesel

Full loan available! Superbly well maintained. Cheap and low depreciation to drive with a peace of mind. STA/workshop check welcome. Trade in/consignment available for your ride. Viewing only by appointment basis. \$0 downpayment, 100% loan available. Contact us today!

Posted 08-Nov-2024

☐ Compare



★ StarAd View All

2023 Toyota Alphard 2.5 S C-Package.

Original Factory Condition, One Owner Unit, Low Mileage. 88 Auto Pte Ltd



KA-HUP
ESTABLISHED SINCE 1989

- VALUE FOR MONEY
- A PEACE OF MIND

HOTLINE: 6741 999



Toyota Hiace Commuter
3.0A High Roof

\$68,888 \$16,950 /yr 12-Dec-2018
(4yrs COE left) 3,140 km
Instl. \$1,489 /mth 2,982 cc 1 Owner Diesel

Borneo unit no adblue needed. Newly wrapped seats and roofing. 4 brand new tyres. Regular servicing done and in good condition. Smooth engine and gearbox. Cheapest in the market.

Posted 07-Nov-2024

☐ Compare

DIRECT OWNER



Toyota Hiace
Commuter 2.8A GL

\$86,800 \$21,770 /yr 14-Nov-2018
(3yrs 11mths COE left) 142,500 km
Instl. \$1,912 /mth 2,754 cc 2 Owners Diesel

Good condition and low mileage done commuter bus. Very well maintained engine, transmission and interior. Selling due to changing trade. View to appreciate. Negotiable for serious buyer.

Posted 24-Oct-2024

☐ Compare

DIRECT OWNER

[Compare](#)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

20 November 2024

REG NO.: PC 7113 G
MAKE/MODEL: TOYOTA HIACE

not Authorised

mercus

19/11/24

2/5 \$ 7000

8 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	\$ NS 120.80 X
1	Rear tailgate	\$ Body 2,362.00 ✓
2	Rear tailgate dampers	\$ 17 694.20 X
1	Rear tailgate inner trim board	\$ 17 450.00 X
1	Rear tailgate lock	\$ 17 450.00 X
1	Rear tailgate logo	\$ 200 80.50
1	Rear tailgate rubber	\$ 200 379.80
1	Rear taillamp -LH	\$ 200 425.00
1	Rear taillamp lower garnish	\$ 200 284.20
1	Rear end panel	\$ 566.10 20/200 869.10
1	Rear end panel inner garnish	\$ 200 190.62
1	Rear taillamp panel LH	\$ 200 624.50
1	Rear keyless sensor	\$ 200 210.00
1	Rear bumper	\$ 735.20 20.5 938.00
1	Rear bumper top bracket	\$ 17 65.00 X
1	Rear bumper side retainer LH	\$ 200 112.40
1	Rear floor panel	\$ 200 1,880.80 X
1	Rear side panel -LH	\$ Body 2,079.70
1	Rear side panel air vent LH	\$ 20.5 98.00
		\$ 12,314.62
	Less 25%	\$ 3,078.66
		\$ 9,235.97

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$ 200 80.00 40
1	Rear tailgate "70KM/H" sticker	\$ 200 25.00 10
1	Rear bumper clip (1 set)	\$ 200 50.00 30
1	Rear side panel sealant	\$ 200 120.00 50
		\$ 275.00

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes seat upholstery	\$ 180.00 100
3	To remove and refit rear windscreen glass.	\$ 180.00 120
4	To remove and refit quarter glass to assist repair.	\$ 150.00 100
5	To apply undercoating.	\$ 200.00 80
6	Panel beating.	\$ 1,800.00 1200
7	To re-spray painting on the affected areas.	\$ 1,600.00 900
		\$ 4,190.00

\$ 13,700.97

the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal Page 1 of 1s allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 8148.02
25-4
611102
130
2520