



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110385/Nvp3e2
16 RAFFLES QUAY	Date:	09/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- OWN DAMAGE CLAIM

Insured Veh.	-	Veh. Inspected	SHA 7884U
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24010145MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	19/11/2024

2. Vehicle Details

Make & Model	HYUNDAI KONA	C.C	1580
Engine No.	G4LLRU405592	Year of Reg.	23/04/2024
Chassis No.	KMHHB811VRU053347	Colour	BLUE
Odometer	- KM	Steering	BURNT
Brakes	BURNT	General	BURNT
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	BURNT	BURNT	BURNT
L/H Front Tyre	BURNT	BURNT	BURNT
R/H Rear Tyre	205/65 R16	KUMHO	4
L/H Rear Tyre	205/65 R16	KUMHO	4

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S, N/S BODY, UNDERCARRIAGE AND ROOFTOP.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/11/2024	Inspection Date	20/11/2024
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE BOOK VALUE IS S\$113,953.87(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.