

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LIBERTY INSURA	NCE PTE LTD	Re	ef:	CS/LIP24110386/Tqh3m4(N)	
	ONE RAFFLES QU	JAY	Da	ate:	14/05/2025	
	#25-01 NORTH TOWERSI	NGAPORE 048583				
	ATTN: ANDY SEAR	Н	Co	ode:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLA 5336B	Veh. Inspected		SNN 8695C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	AVS24/3579	Excess (\$)		0.00	
	Assign From	ANDY SEAH	Assign Date		19/11/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA SIENTA	C.C		1490	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	MXPL101036004	Colour		BLACK	
	Odometer	38545 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/65R15	DUNLOP		6 mm	
	L/H Front Tyre	185/65R15	DUNLOP		6 mm	
	R/H Rear Tyre	185/65R15	DUNLOP		6 mm	
	L/H Rear Tyre	185/65R15	DUNLOP		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	16/11/2024	Inspection Date		20/11/2024	
	Survey held at	CYS AUTOMOBILE SERVICES	PTE LTD			
		38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700				
5a.	Remarks					
	A)REGISTRATION DATE: 28 DEC 2023 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				