



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR MANIVANNAN HARISH KUMAR
BLK. 325A SUMANG WALK
#14-981 SINGAPORE 821325

POLICY NO : THIRD PARTY CLAIM
YOUR REF : SLA 5336 B (LIBERTY)
OUR REF : TP 6731
VEHICLE NO : SNN 8695 C
MAKE/MODEL : TOYOTA SIENTA
DATE OF ACCIDENT : 16.11.24

SURVEY BY

DATE : 18.11.24

- 1 PC TAILGATE
- 1 PC TAILGATE "HYBRID" EMBLEM
- 1 PC TAILGATE TOP LOCK
- 1 PC TAILGATE WEATHERSTRIP
- 1 PC REAR BUMPER
- 1 PC REAR END PANEL *a photo*

S\$ 2,025.90 *bt*
174.00 *acc*
647.90 ?
465.30 ?
1,302.80 *de*
660.50 *Rp*

S\$ 5,276.40

LESS 25% 1,319.10

S\$ 3,957.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- 1 PC TAILGATE GLASS SEALANT
- 1 SET REAR BUMPER CLIPS
- 1 SET REVERSE SENSOR

S\$ *acc* 60.00 S/ NETT

acc 28.00 "

200 ? 400.00 "

S\$ 488.00

TO TRANSFER TAILGATE FITTING

S\$ 100.00 *60*

TO REMOVE AND REFIX TAILGATE GLASS

140.00 *120*

TO TRANSFER REVERSE CAMERA

60.00 *30*

TO DISMANTLE AND REFIX REVERSE SENSOR

50.00 *30*

TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL

100.00 *40*

LABOUR CHARGES

700.00 *500*

TO PUTTY AND SPRAY PAINTING CHARGES

700.00 *600*

S\$ 6,295.30

SIN DOLLARS: SIX THOUSAND ONE HUNDRED NINTY-FIVE AND CENTS THIRTY ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

Tanfhir 97495749/62523561
wp' 20/11/24 e 1145
tanfhir @ lkh and on
4-5 days p/p Resurvey before part