

ASS. REC. BY: Taufikh

REF: 15/11P24110386/Tgh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: 138K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seer: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNN8695C Yr Regn: 2013, 12

Type: M. Car / M. Cyclo / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Toyota Sienta c.c. 1490

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 38545 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MXPL10 103.6004

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 20/11/24

Survey held at LYS

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised final fig \$3995.02, 4 days (Red \$2300.28, 37%)

Date/Time, File Pass to?

1) 14/05 Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2


Add Fee: ☐ : Site Insp (\$ _____)

☐ : Intend. _____

Survey Fee: _____

Transportation: _____

\$ + RS. \$1 _____



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR MANIVANNAN HARISH KUMAR
BLK. 325A SUMANG WALK
#14-981 SINGAPORE 821325

POLICY NO : THIRD PARTY CLAIM
YOUR REF : SLA 5336 B (LIBERTY)
OUR REF : TP 6731
VEHICLE NO : SNN 8695 C
MAKE/MODEL : TOYOTA SIENTA
DATE OF ACCIDENT : 16.11.24

SURVEY BY

DATE : 18.11.24

- 1 PC TAILGATE
- 1 PC TAILGATE "HYBRID" EMBLEM
- 1 PC TAILGATE TOP LOCK
- 1 PC TAILGATE WEATHERSTRIP
- 1 PC REAR BUMPER
- 1 PC REAR END PANEL *a photo*

S\$ 2,025.90 *bt*
174.00 *acc*
647.90 ?
465.30 ?
1,302.80 *de*
660.50 *Rp*

S\$ 5,276.40

LESS 25% 1,319.10

S\$ 3,957.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- 1 PC TAILGATE GLASS SEALANT
- 1 SET REAR BUMPER CLIPS
- 1 SET REVERSE SENSOR

S\$ *acc* 60.00 S/ NETT

acc 28.00 "

200 ? 400.00 "

S\$ 488.00

TO TRANSFER TAILGATE FITTING

S\$ 100.00 *60*

TO REMOVE AND REFIX TAILGATE GLASS

140.00 *120*

TO TRANSFER REVERSE CAMERA

60.00 *30*

TO DISMANTLE AND REFIX REVERSE SENSOR

50.00 *30*

TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL

100.00 *40*

LABOUR CHARGES

700.00 *500*

TO PUTTY AND SPRAY PAINTING CHARGES

700.00 *600*

S\$ 6,295.30

SIN DOLLARS: SIX THOUSAND ONE HUNDRED NINTY-FIVE AND CENTS THIRTY ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

Tanfhir 97495749/62523561
wp 20/11/24 e 1145
tanfhir @ lkh and on
4-5 days p/p Resurvey before part