

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

Not Authorised
 as
 new
 20/11/24
 2/4 # 1300/
 2 days.
 Unhappy Harry.

VEHICLE No: SDZ 51T

1PC	FRONT BUMPER	De/To. 1	\$820.00	✓
1PC	FRONT BUMPER LOWER CENTRE GRILLE	11	\$105.00	×
2PCS	FRONT BUMPER SIDE RETAINERS @\$145.00	11	\$290.00	×
1PC	FRONT BUMPER REINFORCEMENT	R	\$920.00	×
2PCS	FRONT BUMPER REINFORCEMENT BRACKETS @\$255.00	11	\$510.00	×
1PC	FRONT BUMPER TOP CENTRE GRILLE	11	\$280.00	×
1PC	FRONT BUMPER TOW COVER	11	\$30.00	×
1SET	FRONT BUMPER CLIPS	11	\$50.00	✓
1PC	FRONT GRILLE	11	\$860.00	✓
1PC	FRONT GRILLE 'H' LOGO	11	\$35.00	×
1PC	FRONT SUPPORT PANEL	R	\$615.00	×
			\$4,515.00	
LESS 20%			\$3,612.00	

TO CHECK WIRING	\$50.00	20
TO REFILL AIR CON GAS	\$120.00	11
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$500.00	200
TO PUTTY & SPRAY PAINTING	\$600.00	300
TOTAL	\$4,882.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2-14152
 202
 113216
 520
 165216
 202
 1321