



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLQ 561R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RH FENDER	DENTED	\$586.00	\$586.00
1	RH FENDER DUST GARNISH	NOT NECESSARY	\$152.80	\$0.00
10	RH FENDER DUST GARNISH CLIP @\$6.00	NOT NECESSARY	\$60.00	\$0.00
1	RH HEAD LAMP ASSY	MTG BROKEN	\$1,658.70	\$1,658.70
1	RH HEAD LAMP LOWER BRACKET RH	NOT NECESSARY	\$59.00	\$0.00
1	FRONT BUMPER	CUT	\$991.80	\$991.80
1	FRONT BUMPER RETAINER	BROKEN	\$37.46	\$37.46
1	BONNET	NOT NECESSARY	\$991.00	\$0.00
1	GRILLE ASSY	NOT NECESSARY	\$1,099.00	\$0.00
1	SPORT RIM	NOT NECESSARY	\$599.00	\$0.00
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$654.79)
			\$6,234.76	\$2,619.17

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & RENEW SPORT RIM & REBALANCING	NOT NECESSARY	\$80.00	\$0.00
	TO CHECK WIRING & REMOVE & REFIT ALL WIRING FOR ALL ACCIDENT AFFECTED AREA		\$180.00	\$30.00
	TO KNOCKING, STRAIGHTENING, REPAIR & RENEW ALL ACCIDENT AFFECTED AREA		\$1,000.00	\$300.00
	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA		\$1,000.00	\$400.00
			\$2,260.00	\$730.00

GRAND TOTAL	\$8,494.76	\$3,349.17
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,600.00
---	--	-------------------

Report Ref No: CS/INC24110389/Dnh3m4

TOTAL FOR SPARE PARTS: \$ 6,234.76 \$ 2,619.17
TOTAL FOR LABOUR : \$ 2,260.00 \$ 730.00
TOTAL REPAIR COST: \$ 8,494.76 \$ 3,349.17

ABT

ANG BRYAN TANI



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.