



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Key tag - 3112

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBS5331M
MAKE/MODEL : HON / MONKEY 125 M

QUOTATION

NO. : 46891

Repair Sum
\$ 4300

DATE : 25/06/2024
CLAIM NO. : 12524
POLICY NO. : MC/01365208
FROM : RAYMOND

not actual
4 days
27/6/24
take photo

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	57.00
2	BAG WATERPROOF (ROCKBROS) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	140.00
3	BALANCER HANDLE SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	140.00
4	BALL ASSY STEERING CONE P/N: 54553 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
5	BAR HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$107.00	107.00
6	BOLT FOOTREST P/N: 55687 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
7	BOLT FOOTREST 1 P/N: 55691 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$9.00	18.00
8	BRACKET FOOTREST FRONT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$141.00	141.00
9	BRACKET UNDER FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$377.00	377.00

*46891 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance



DATA PROTECTION
ASSURED

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	COVER HEADLIGHT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$259.00	259.00 <i>Daye</i>
11	COVER METER LOWER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$107.00	107.00 <i>CUT</i>
12	FENDER REAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$200.00	200.00 <i>Daye</i> X
13	FOOTREST ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$542.00	542.00 <i>M.S</i>
14	FORK LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$916.00	916.00 <i>R</i> X
15	FORK RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$916.00	916.00 <i>Su</i> X
16	HEADLIGHT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$518.00	518.00 <i>CM</i>
17	HOLDER LEVER LH P/N: 64328 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	36.00 <i>CUT</i>
18	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	Supply/Install	7.00	\$85.00	595.00 <i>480</i>
19	LEVER CLUTCH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	36.00 <i>CUT</i>
20	METER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$893.00	893.00 <i>CUT</i>
21	MIRROR COMP. P/N: 83238 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$107.00	107.00 <i>CUT</i>
22	NUT SUSPENSION (GCRAFT) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$236.00	236.00 <i>Daye</i>
23	OBU TYPE B (12V) NEW P/N: 82490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00 <i>Daye</i> X
24	PEDAL GEAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	90.00 <i>CUT</i>

*46891 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	PLATE FOOTREST P/N: 25287 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	Surf 17.00
26	PLATE FOOTREST LH P/N: 71327 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$76.00	me's 76.00
27	RACE STEERING TOP BALL - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	TH 1 20.00 X
28	RIM FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$893.00	R 893.00 X
29	RUBBER COVER FOR CLUTCH LEVER P/N: 27083 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$29.00	1 1 29.00 X
30	RUBBER GEAR PEDAL P/N: 25818 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	CUT 6.00
31	RUBBER, MAIN STEP P/N: 83217 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$29.00	me 29.00
32	SEAT COMP SINGLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$423.00	Tom 423.00
33	SIGNAL REAR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$189.00	CUT 189.00
34	SLIDER ENGINE SET P/N: 80239 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$434.00	CUT 434.00
35	STAND SIDE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$67.00	(CUT) 67.00
36	STEERING RACE P/N: 50032 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	TH 51.00 X
37	TRANSPORT CHARGES P/N: 07169 -- ONE WAY TOWING		1.00	\$62.00	35 62.00
38	VALVE RIM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	1 1 X 25.00
39	WEIGHT A, HANDLE P/N: 83216 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	TH 43.00 X

SUB TOTAL
GST @ 9 %

\$9,161.00
\$824.49

*46891 *



bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL (SGD)					\$9,985.49

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By




RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

P. 4650
102
4185.20
609
4794
102
4314

*46891 *





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

NO. : 46922 - Rev. 1

Supplementary 1 To QTN: 46891

DATE : 28/06/2024
CLAIM NO. : 12524
POLICY NO. : MC/01365208
FROM : STEPHANIE

VEHICLE NO. : FBS5331M
MAKE/MODEL : HON / MONKEY 125 M

S/N	Description	Action	Qty	Unit Price	Amount
1	REPAIR BRACKET UNDER FORK	Repair	1.00	\$140.00	140.00
2	REPAIR FORK LH <i>Lober</i>	Repair	1.00	\$125.00	125.00
3	OIL ENGINE (MOBIL) SUPER MOTO SYN TEC 10W/40 P/N: 72839	Replace	1.00	\$14.00	14.00
4	PROTECTOR, R. COVER P/N: 83232	Replace	1.00	\$44.00	44.00
SUB TOTAL					\$323.00
GST @ 9 %					\$29.07
GRAND TOTAL (SGD)					\$352.07

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*46922 *

