

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LONPAC INSURAN	CE BHD	Ref:	CS/LPC24110391/Evh3e2	
	300 BEACH ROAD	NCOURSE SINGAPORE 199555	Date:	12/12/2024	
	#17-04/07 THE CON	VOCONGE GINGAI GIVE 199000	Code:	LPC2	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJB 4761G	Veh. Inspected	SBS 3650E	
	Policy No.	-	Coverage	0	
	Claim No.	24/24/24/VP05/030186	Excess	\$0.00	
	Assign From	CHARMAINE KONG	Assign Date	19/11/2024	
2.	2. Vehicle Details				
	Make & Model	VOLVO B9TL	C.C	9364	
	Engine No.	D9190858	Year of Reg.	13/09/2013	
	Chassis No.	YV3S4P929DA162172	Colour	MULTI COLOUR	
	Odometer	573618 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	275/70 R22.5	BRIDGESTONE	5	
	L/H Front Tyre	275/70 R22.5	BRIDGESTONE	5	
	R/H Rear Tyre	275/70 R22.5	BRIDGESTONE	5	
	L/H Rear Tyre	275/70 R22.5	BRIDGESTONE	5	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
	Accident Date	15/11/2024	Inspection Date	27/11/2024	
	Survey held at	SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946			
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days