



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS/LPC24110394/Uqh3m4
300 BEACH ROAD	Date:	03/12/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 3327G	Veh. Inspected	GBG 5855G
Policy No.	Z24VC05023626	Coverage	0
Claim No.	24/24/24/VC05/030201	Excess	\$0.00
Assign From	GERALD	Assign Date	19/11/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE (M)	C.C	2982
Engine No.	1KD2750128	Year of Reg.	08/09/2017
Chassis No.	JTFHT02P800233295	Colour	SILVER
Odometer	227933 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	GETWIN	6
L/H Front Tyre	195R15	GETWIN	6
R/H Rear Tyre	195R15	GETWIN	6
L/H Rear Tyre	195R15	GETWIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/11/2024	Inspection Date	20/11/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days