

Not Notified
 L1 Sy @ 3350h
 Repair After Rain
 4 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SNK 3028C

Acc: 16.11.24

S/N	Parts Description
1	Rear tailgate emblem
2	Tailgate assy
3	Rear bumper
4	Rear bumper reinforcement
5	Rear bumper inner bracket
6	Rear bumper lower garnish
7	Rear bumper lower garnish mldg
8	Rear bumper innergarnish
9	Rear end panel
10	Rear end panel top garnish
11	Rear exhaust chrome cover LH

Unit Price	Amt
na	\$80 ✓
R	\$1,645 X
Bu	\$1,409.00 ✓
By	\$568.00 ✓
CM	\$135.00 ✓
Od / mldg	\$485.00 ✓
ad	\$186.00 ✓
CM	\$208.00 ✓
R	\$990.10 X
su	\$185.10 X
ad	\$325.00 ✓

109

Labour

1 To remove and refit damaged parts	\$900.00 600
2 To spray paint on affected parts	\$1,000.00 450
3 To remove and refit rear reverse sensor	\$120.00 60
4 To remove and refit rear garnishes	\$120.00 50
5 Tuff coat on affected parts	na \$100.00 X
6 To check wiring	\$50.00 15
	<hr/> \$2,290.00

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: