

REF: CS/AGI24110398/Avp3

ASSIGNMENT

Front: _____ Date: _____

Estm: _____

OD / TP RES / CD RES / EVA / INV / MVTo in Vehicle No: _____at W 1000 m/s _____

of _____

Insured: SLN 8251Z

Policy No: _____

Claims No: C10032942/JK

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: There had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC8004D Yr Regn: 2016, May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 6 CO: 1998Colour: Black A/C: Insured / Std / NI / NASp. Reading: 12297 T/Radio: Insured / Std / NI / NAEng/No: 122157C/No: JM6GJ1072G0232636

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18R: 245/45R18

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. 16/11/2024 D.O.I. 02/12/24Survey held at: Modern

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Budget Direct.</u>
<u>27/3/25</u>	<u>Adrian confirmed LS \$3100 (red 3571.60, 53%)</u>
	<u>COE Expiry :</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?

☐ : Prelim. ReportDays Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee:

Transportation:

3 + P.S. \$1

Photos

Others

Report Form:

Report Form:

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

Auto & General Insurance (Singapore) Pte. Limited
trading as Budget Direct Insurance

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924

Tel: 6221 2199

Quotation

DATE : 20.11.2024
VEH NO : SLC8004D
MODEL : Mazda 6
D O A : 16.11.2024
YR REF : SLN8251Z

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8004D (MAZDA 6)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Front Bumper <i>behind</i>	1	1,200.00 ✓
2	Front Bumper Bracket - LH & RH <i>new</i>	2	92.00 ✓
3	Front Bumper Side Retainer - LH & RH <i>new</i>	2	35.00 +
4	Front Bumper Chrome Moulding - RH <i>new</i>	1	180.00 ✓
5	Fog Lamp - RH <i>new</i>	1	760.00 +
6	Front Fender - RH <i>new</i>	1	385.00 ✓
7	Headlamp - RH <i>new</i>	1	4,100.00 ✓
8	Headlamp Panel - RH <i>new</i>	1	150.00 +
			6,902.00
	Less 20%		(1,380.40)
	Total parts		\$ 5,521.60

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$ 600.00 <i>300</i>
2	To putty & spray up paint works	\$ 500.00 <i>200</i>
3	To check wiring system	\$ 20.00 ✓
4	To underseal	\$ 30.00 X
		\$ 1,150.00
	Grand Total	\$ 6,671.60

Acknowledged by Repairer

Signature:

GST Will be reflected in the final bills

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• To underseal subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Adrian L
L/s 02/14/24
03 Days