

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP / RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remarks: There had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLC8004D Yr Regn: 2016, May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 6 CO: 1998

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 123297 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6GJ1072G0232636

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18

R: 245/45R18

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 02/12/24

Survey held at Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front of

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Budget Direct

COE Expiry :

Estimate given during : Yes (✓)

1st Survey : No ()

MV :

PV :

Nett :

Date/Time, File Pass to?

☐ : Prelim. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + P.S. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Form: _____

Report Form: _____

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel :67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

Auto & General Insurance (Singapore) Pte. Limited
trading as Budget Direct Insurance

190 Clemenceau Avenue, #03-01
 Singapore Shopping Centre
 Singapore 239924

Tel: 6221 2199

Quotation

DATE : 20.11.2024
 VEH NO : SLC8004D
 MODEL : Mazda 6
 D O A : 16.11.2024
 YR REF : SLN8251Z

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8004D (MAZDA 6)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	<u>LIST ITEMS</u>		
1	Front Bumper <i>behind</i>	1	1,200.00 ✓
2	Front Bumper Bracket - LH & RH <i>new</i>	2	92.00 ✓
3	Front Bumper Side Retainer - LH & RH <i>new</i>	2	35.00 +
4	Front Bumper Chrome Moulding - RH <i>lt</i>	1	180.00 ✓
5	Fog Lamp - RH <i>new</i>	1	760.00 +
6	Front Fender - RH <i>new</i>	1	385.00 ✓
7	Headlamp - RH <i>lt</i>	1	4,100.00 ✓
8	Headlamp Panel - RH <i>new</i>	1	150.00 +
			6,902.00
	Less 20%		(1,380.40)
	Total parts		\$ 5,521.60

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$ 600.00 <i>300</i>
2	To putty & spray up paint works	\$ 500.00 <i>200</i>
3	To check wiring system	\$ 20.00 ✓
4	To underseal	\$ 30.00 X
		\$ 1,150.00
	Grand Total	\$ 6,671.60

LKK Auto Consultants hence notify
 the Repairer of the following
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • To underseal subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

GST Will be reflected in the final bills

Adrian L
L/s 02/14/24
03 Days