



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS INCOME INSURANCE LTD		Ref:	CS3/INC24110399/Eqh3m4	
75 BRAS BASAH ROAD		Date:	25/11/2024	
INCOME CENTRE SINGAPORE 189557		Code:	INC	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	SLZ 7368P	Veh. Inspected	SNK 3526G	
Policy No.	-	Coverage	0	
Claim No.	MT/1304521-002	Excess	\$0.00	
Assign From	AZHARI AFIDI	Assign Date	19/11/2024	
2. Vehicle Details				
Make & Model	TOYOTA SIENTA HYBRID	C.C	1490	
Engine No.	M15AY502917	Year of Reg.	06/04/2023	
Chassis No.	MXPL101014181	Colour	BEIGE	
Odometer	51569 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	205/55R16	FALKEN	6	
L/H Front Tyre	205/55R16	FALKEN	6	
R/H Rear Tyre	205/55R16	FALKEN	6	
L/H Rear Tyre	205/55R16	FALKEN	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	17/11/2024	Inspection Date	19/11/2024 (11:28)	
Survey held at	POSH AUTOWERKZ PTE LTD - 8 KAKI BUKIT AVE 4 #02-24, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

CTY

CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.