



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

8 July 2024

Not Authorised

27/6/24

4/5 @ 3800

REG NO.: SLX 4119 Y
MAKE/MODEL: MITSUBISHI SPACE STAR

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
<u>NETT LIST ITEMS</u>		
1	Rear windscreen moulding NS	\$ 78.00 X
1	Rear tailgate Body DD	\$ 764 1,339.65
1	Rear tailgate inner lock Damage	\$ 145 200.64
1	Rear tailgate weatherstrip TMI	\$ 111 488.31
1	Rear tailgate logo NEU	\$ 60 111.31
1	Rear tailgate "SPACE STAR" emblem NEU	\$ 48 90.97
1	Rear tailgate "MIVEC" emblem NEU	\$ 48 89.89
1	Rear tailgate outer handle 11	\$ 245.00 X
2	Rear taillamps 11	\$ 1,376.66 X
1	Rear end panel Body DD	\$ 448 600.74
1	Rear end panel inner trim TMI	\$ 122.31
1	Rear end keyless sensor CRG	\$ 101 288.96
2	Rear fenders 2	\$ 2,435.30 X
2	Rear fender inner trims 11	\$ 977.92 X
1	Rear bumper DE/TO-1	\$ 789 988.74
2	Rear bumper lower brackets 11	\$ 223.30 X
2	Rear bumper reflectors 11	\$ 243.10 X
1	Rear floor panel top board 11	\$ 162 197.50
2	Rear number plate lamps CRG/TMI	\$ 96.00
		\$ 10,194.30
Less 10%		\$ 1,019.43
		\$ 9,174.87

SPECIAL NETT ITEMS

1	Rear windscreen sealant NEU	\$ 80.00 40
1	Rear tailgate "C&C" emblem NEU	\$ 40.00
1	Rear bumper clip (1 set) NEU	\$ 60.00 30
1	Rear number plate Damage	\$ 50.00 35
1	Rear reverse sensor (1 set) SU	\$ 350.00 X
		\$ 580.00

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 180.00 60
3	To remove and refit rear reverse sensor.	\$ 180.00 30
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 80.00 50
5	To remove and refit rear windscreen glass.	\$ 180.00 120
6	To apply undercoating.	\$ 150.00 50
7	Panel beating.	\$ 2,000.00 800
8	To re-spray painting on the affected areas.	\$ 1,800.00 900
		\$ 4,650.00

GRAND TOTAL :

\$ 14,404.87

2894.31
102
2604.88
145
2030