

VIN S

Estimated Cost of Repair

Attention To : **ECICS LIMITED**
 7 Temasek Boulevard
 #10-01 Suntec Tower One
 Singapore 038987

Claim Details

Case Ref. No. : OD/112024/7857
 Date : 18-11-2024
 Accident Date : 16-11-2024

Vehicle Details

Make & Model : B.M.W. 520I AT D/AB 2WD 4DR
 LED NAV
 Chassis No : WBA5A32060D790590
 Registration No : SCF111X

Not Authorized
Kenneth (Ukk) L1 Rmp &
Resony After Rain
4 days Ex @1250/

S/N	Description	Qty	Amount (\$)	
1	FRONT BONNET	1.00	Bz \$2,100.00	✓
2	BONNET RH HINGE	1.00	R \$150.00	X
3	BONNET LH HINGE	1.00	R \$150.00	X
4	BONNET RH LOWER LOCK	1.00	\$210.00	7
5	LH GRILLE	1.00	Pa \$240.00	✓
6	RH GRILLE	1.00	Pa \$240.00	✓
7	RH HEADLAMP	1.00	Bu \$3,600.00	✓
8	RH HEADLAMP SUPPORT HOUSING Pr?	1.00	\$3,600.00	7 4
9	RH HEADLAMP WASHER SPRAY	1.00	\$160.00	7
10	FRONT BUMPER	1.00	Bu \$1,200.00	✓
11	FRONT BUMPER EMBLEM	1.00	na \$90.00	✓
12	FRONT BUMPER TOWING COVER	1.00	su \$60.00	X
13	FRONT BUMPER PARKING SENSOR @ CENTER	2.00	\$400.00	7
14	FRONT BUMPER CENTER LOWER GRILLE	1.00	\$140.00	7
15	FRONT BUMPER RH FOG LAMP COVER	1.00	su \$90.00	X
16	FRONT BUMPER RH SIDE RETAINER	1.00	Ort \$20.00	✓
17	FRONT BUMPER LH SIDE RETAINER	1.00	su \$20.00	X
18	FRONT BUMPER SPONGE	1.00	\$110.00	7
19	FRONT BUMPER REINFORCEMENT	1.00	\$650.00	7
20	FRONT BUMPER LOWER BEAM	1.00	\$180.00	7
21	FRONT BUMPER UNDER COVER	1.00	su \$330.00	X
22	FRONT BUMPER CLIPS	10.00	na \$20.00	✓
23	FRONT SUPPORT PANEL	1.00	\$260.00	7
24	RADIATOR AIR DUCT	1.00	\$430.00	7
			\$14,450.00	
Margin: 10%			\$1,445.00	
			\$15,895.00	
25	FRONT NO.PLATE	1.00	Bz \$40.00	✓
26	TO REFILL AIRCON GAS	1.00	na \$150.00	X

VINS

REF:

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

27 TO RESET HEADLAMP SYSTEM
28 TO REPAIR DAMAGES
29 TO SPRAY PAINTING

1.00 \$280.00
1.00 500l \$780.00
1.00 500l \$880.00

Subtotal w/o GST: \$18,025.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4