

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 20 Nov 2024

**Preliminary Advice**

Vehicle No	: SCF111X	Accident Date	: 16/11/2024
Make	: BMW 520I	Policy No.	: MPC23A00383602
Assignment Date	: 19/11/2024	Excess	: S\$1,250.00
Date of Inspection	: 20/11/2024	Est. Duration of Repair	: 4
Inspection At	: VIN'S MOTOR PTE LTD (SIN MING) 20 SIN MING LANE, #06-65 MIDVIEW CITY SINGAPORE 573968		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,351.00
Revised Amount	:S\$	9,321.00
Check Items (Estimated)	:S\$	3,080.00
Total	:S\$	12,401.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	26,941.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,059.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Repairer able to undertake the repair cost not more than \$7,500.00.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.