

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24110403/KVP3M4(N)**Date:** 06/01/2025**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZD06899
Claimant Vehicle No :	SMU3698C	Insured Vehicle No :	GBH7497M
Date of Loss:	17/11/2024	Nature of Claim:	TP
		Claim No:	M2406718

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU3698C		
Make & Model:	PEUGEOT 5008, 1.6 ALLURE 1.6 E-THP EAT6 (A)	Engine No:	10FJCS2475645
Reg. Date:	10/06/2019 (Man. Year: 2018)	Chassis No:	VF3M45GZWJL052361
Colour:	Metallic Blue	Odometer:	112613 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,655.00	1,579.50	1,075.50	40.51
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,600.00	1,000.00	600.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,267.00	2,591.50	1,675.50	39.27
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	4,267.00	2,050.00	2,217.00	51.96
+ GST 9.00/9.00% (S\$)	384.03	184.50	199.53	51.96
Nett Amount (S\$)	4,651.03	2,234.50	2,416.53	51.96

INSPECTION

Date of Assignment:	20/11/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell) COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701
Date Inspected:	21/11/2024	Inspected At:	
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2025)
Parts:	M1-SUV	PEUGEOT 5008 1.6 ALLURE 1.6 E-THP EAT6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU3698C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR FENDER ARCH	Cut	300.00 F	*300.00 F
2	1		*RH REAR RIM	Repair	830.00 F	*- F
3	1		*REAR BUMPER	Cut	1,820.00 F	*1,455.00 F
						F=Franchise part.
					Sub Total (S\$)	2,950.00
					- Add. Disc. on L,N Items 10.00/10.00% (S\$)	295.00
					Total Parts (S\$)	2,655.00
						1,755.00
						1,579.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT REMOVE AND REFIT NECESSARY	New	800.00	400.00
2	TO SPRAY PAINT AND PUTTY NECESSARY	New	800.00	600.00
Gross Labour Cost (\$\$)			1,600.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >