

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email:

tanpw@cdge.com.sg; kelvinsukwen@cdge.com.sg; oisunpin@cdge.com.sg; joharibh@sparkcarcare.com; kristytay@sparkcarcare.com

TP INSURER:
TAY KIAN AUN

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/11/2024
Vehicle Reg. No.:	SMU3698C	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	PEUGEOT 5008, 1.6 ALLURE 1.6 E-THP EAT6 (A)	Vehicle Reg. Date:	10/06/2019
Vehicle Colour:	BLUE	Gen Condition:	EXCELLENT
Engine No:	10FJCS2475645	Chassis No:	VF3M45GZWJL052361
Odometer:	112452 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3 ✓		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

NOT AUTHORISED
Runway After Rain
11/11/24 @ 2050h

COST OF CLAIMS

	Amount
Parts	2,655.00
Miscellaneous Items	12.00
Labour	1,600.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,267.00
+ GST 9.00% (S\$)	384.03
Nett Amount (S\$)	4,651.03

This claim is handled by: ABDUL HAKIM BIN ABDUL HAMID

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Nov 2024)
Parts: M1-SUV PEUGEOT 5008 1.6 ALLURE 1.6 E-THP EAT6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMU3698C)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RH REAR FENDER ARCH	0.00	0.00	*300.00 F
2	1		*RH REAR RIM	0.00	0.00	*830.00 F
3	1		*REAR BUMPER	0.00	0.00	*1,820.00 F
Sub Total (S\$)						2,950.00
- Add. Disc. on L,N Items 10.00% (S\$)						295.00
Total Parts (S\$)						2,655.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

12.00

1 1 OD/TP Case (Insurer)

Sub Total (S\$)

12.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

- 1 TO PANEL BEAT REMOVE AND REFIT NECESSARY
- 2 TO SPRAY PAINT AND PUTTY NECESSARY

New

800.00

New

800.00

Gross Labour Cost (S\$)

1,600.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >