



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 7065K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR RH DOOR	DENTED	1,448.00	1,448.00
1	REAR RH DOOR INNER TRIM	NOT NECESSARY	771.00	-
1	REAR RH DOOR LOCK	NOT NECESSARY	659.00	-
1	REAR BUMPER	DISTORTED	805.00	685.00
1	REAR RH BUMPER RETAINER	NOT NECESSARY	183.00	-
1	REAR RH FENDER	DISTORTED	1,572.00	1,345.00
1	REAR WHEEL HOUSE OUTER PANEL	TO REPAIR SEE LABOUR	355.00	-
	LESS 25% DISCOUNT		-1,448.25	-869.50
			4,344.75	2,608.50
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR DOOR CLIPS (SN)	NOT NECESSARY	50.00	-
			150.00	30.00
<u>LABOUR</u>				
	TO PUTTY AND SPRAY PAINTING.		600.00	600.00
	WIRING CHARGES.		60.00	30.00
	TUFF COAT.		60.00	30.00
	TO REMOVE, REPLACE DOOR FITTING TO FACILITIES REPAIRS.		100.00	60.00
	LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT AND REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR WHEEL HOUSE OUTER PANEL.		800.00	700.00
			1,620.00	1,420.00
GRAND TOTAL			6,114.75	4,058.50

Report Ref No. CS/INC24110404/Aqh3e2(N)



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,200.00
---	--	--	-----------------

Report Ref No. CS/INC24110404/Aqh3e2(N)

TOTAL FOR SPARE PARTS: \$ 4,494.75 \$ 2,638.50

TOTAL FOR LABOUR : \$ 1,620.00 \$ 1,420.00

TOTAL REPAIR COST: \$ 6,114.75 \$ 4,058.50

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.