

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Vern

GBL8418P

ESTIMATE OF REPAIR

Veh# : GBL8414P

Model: TOYOTA TOWN ACE

Accident Date : 7/11/2024

29/4/2022

Location : WOODLAND AVE 5

3P: FBT6634C (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tailgate 70 KM/H sticker		25.00 15	
2	1 pc	Rear tailgate GI sticker		80.00 50	
3	1 pc	Rear tailgate Logo	72.20	✓	
4	1 pc	Rear tailgate inner trim board	244.10	✗	
5	1 set	Rear tailgate inner trim garnish clip		50.00	✗
6	1 pc	Rear bumper A52159-B1310 A0	1269.30	1080	
7	1 pc	Rear bumper side retainer RH A52155-B1090	100.9	✗	
8	1 pc	Rear taillamp LH 81550-BZ620	672.70	485	
9	1 pc	Rear taillamp clip RH		30.00	✗
10	1 pc	Rear taillamp lower garnish Rh	257.00	✓	
11	1 pc	Rear taillamp lower garnish retainer Rh	54.90	✗	
		Sub-Total:	2,671.10	185.00	0.00
		1822 S/N: 65	25%	0%	0%
		136650 After Less %:	2,003.33	185.00	0.00
		Labour			
1		To remove & refix accident damaged parts & realign affected area.		800.00 300	
2		To spray paint on accident affected area.		600.00 500	
3		To check wiring		60.00 30	
		Sub-Total:		1,460.00	
		Total:		3,648.33	
		After Less 20%:		2,918.66	

Chan San Choon
Director
DipEng, AAE MIMI, MSAAE (Aust)



Date:

Acknowledged by Repairer



AL 8778 1999
24 hr accident call



Admin L
2/5 20/11/24.

03 Days.

total: 2261.50
L/S: 1.8K ✓