

Hui Rong

ESTIMATE OF REPAIR

Veh# : SKU3472K

Model: MERCEDES BENZ A180
21/7/2015

Accident Date : 15/11/2024

Location : PIE TOWARDS TUAS

3P: SMX70141 (INCOME)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear taillamp RH	729.50	+	
2	1 pc	Rear taillamp lower bracket RH	72.00	+	
3	1 set	Rear taillamp clip RH		30.00	+
4	1 pc	Rear bumper	1,664.50	✓ (1340)	
5	1 pc	Rear bumper centre retainer	210.40	✓	
6	1 pc	Rear bumper diffuser	480.00	360	
7	1 pc	Rear bumper side retainer RH	110.40	+	
8	1 pc	Rear bumper tow hook cover	62.00	+	
9	1 pc	Rear bumper reinforcement	690.50	+	
10	4pcs	Rear bumper reverse sensor	1,226.40	265	
11	4 pcs	Rear bumper reverse sensor 'O' ring	52.00	25	
12	4 pcs	Rear bumper reverse sensor holder bracket	60.00	25	
13	1 set	Rear bumper clip		50.00	30
14	1 pc	Rear boot C&C logo		60.00	+
15	1 pc	Rear boot logo	135.00	+	
16	1 pc	Rear boot A180 logo	710.00	+	
		Sub Total:	6,202.70	80.00	0.00
			10%	0%	0%
		After Less %:	5,582.43	80.00	0.00

2215.40

S/V: 30

1993.86

		Labour	
1		To remove & refix accident damaged parts & realign accident affected area.	800.00 200
2		To spray paint on accident affected area.	600.00 200
3		To rust proof affected area.	80.00 x
4		To check wiring & rewire parking sensor.	80.00 50
5		To diagnosis & reset after work.	250.00 x
		Sub Total:	1,810.00
		Total:	7,472.43

Chan

Chan San Choon
Director
Deying, AAE, MINILMSAE(Aust)

Action Lj
h/s 20/11/24
02 Rys



AL 8778 1999
24 hr accident call



total: 2473.86

L/S: 1.9K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: