



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLL1552L HONDA VEZEL HYBRID

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy with lower lip <i>new</i>	\$ 950.00 <i>+</i>
2	1	Rear bumper side bracket-rear left <i>new</i>	\$ 140.00 <i>45</i>
3	1	RL-bumper side cover-white <i>new</i>	\$ 320.00 <i>190</i>
4	1	Left side air vent-rear left <i>new</i>	\$ 105.00 <i>+</i>
5	1	Rear reflector <i>new</i>	\$ 150.00 <i>+</i>
6	1	Rear fender light left <i>new</i>	\$ 880.00 <i>+</i>
7	2	Rear bumper sensor <i>new</i>	\$ 500.00 <i>+</i>
8	1	Rear bumper lower small trim cover <i>new</i>	\$ 90.00 <i>+</i>
9	1	RL wheel arch trim -Arc shape <i>cut</i>	\$ 280.00 <i>175</i>
10	1	RL wheel arch proofing <i>new</i>	\$ 250.00 <i>+</i>
11	1	Honda rim-rear left <i>cut</i>	\$ 880.00 <i>450 (SN)</i>
12	1	Rim cover <i>new</i>	\$ 80.00 <i>+</i>
13	1	RR-bumper side cover-white <i>Repeated</i>	\$ 320.00 <i>+</i>
14	1	Rear left side panel <i>new</i>	\$ 850.00 <i>+</i>
15	1	Rear left wheel bearing <i>new</i>	\$ 450.00 <i>+</i>
16	1	Rear tailgate light <i>new</i>	\$ 680.00 <i>472</i>
Parts Sub-total			\$ 6,895.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLL1552L HONDA VEZEL HYBRID

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips <i>new</i>	\$ 100.00 <i>30</i>
2	10	Rear bumper lower lip clips <i>new</i>	\$ 100.00 <i>+</i>
3	8	Rear left soundproofing clips <i>new</i>	\$ 80.00 <i>+</i>
4	10	Rear wheel arch clips <i>new</i>	\$ 80.00 <i>20</i>
5	1	Rear number plate and casing <i>new</i>	\$ 120.00 <i>+</i>
6	1	Sealant for side panel body work <i>new</i>	\$ 50.00 <i>+</i>
Special Nett Items Total			\$ 530.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SLL1552L

Modle: HONDA VEZEL HYBRID

No	Description	Labour Charges
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00 30
2	Carry up body cavity preservation for affected area \$50 per panel	\$ 200.00 60
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 1,500.00 300
4	Spray painting for accident affected damaged area, including: bumper, rear end side panel, touch up side cover and rear left door	\$ 1,200.00 200 500
5	Carry out wheel alignment	\$ 120.00 80
6	Removing and installing rear fender compartment garnish, trimming etc, to facilitate the necessary repair and welding work on fender	\$ 150.00 +
7	Checking central lock system for proper function	\$ 120.00 +
8	Remove & install bumper sensor and harness, check for proper function	\$ 120.00 +
9	Water test after accident repair body work	\$ 120.00 +
10	Checking rear fender light wiring and proper function	\$ 80.00 <
11	Carry out diagnosis check including cleaning accident fault code	\$ 150.00 +
Total labour :		\$ 3,840.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li
h/s 20/11/24.

03 Days