

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorized  
in  
Morris  
27/6/24  
d/c \$7000/  
The photo. After rep -  
7 days.

VEHICLE No: SNJ 7491B

1PC	REAR WINDSCREEN MOULDING	11		\$110.20	X
1PC	TAILGATE	2		\$1,499.20	X
1PC	TAILGATE OUTER PANEL COVER	1		\$980.20	X
1PC	TAILGATE 'VEZEL' EMBLEM	11		\$66.80	X
1PC	TAILGATE REFLECTOR O/S	8/10		\$700.00	X
1PC	TAILGATE INNER LOCK	11		\$199.80	X
1PC	TAILGATE LOCK STRIKER	11		\$66.00	X
1PC	TAILGATE INNER TRIM BOARD	11		\$435.00	X
1SET	TAILGATE INNER TRIM BOARD CLIPS	11		\$50.00	X
1PC	TAILGATE WEATHERSTRIP	11		\$288.00	X
1PC	REAR BUMPER TOP	Dis	892.00	\$980.00	—
1PC	REAR BUMPER CENTRE	Dis	650.00	\$870.20	—
1PC	REAR BUMPER UNDER COVER	11		\$541.00	X
1SET	REAR BUMPER CLIPS	11		\$50.00	—
1PC	REAR BUMPER REFLECTOR O/S	one		\$65.00	—
1SET	REAR BUMPER CLIPS	11		\$50.00	—
1PC	REAR BUMPER SIDE RETAINER	Dis one		\$45.00	—
1PC	REAR END PANEL	Dis/bent	547.00	\$665.20	—
1PC	REAR END PANEL TOP GARNISH	11		\$341.10	X
1PC	TAILLAMP O/S	11	681.20	\$900.00	—
1PC	TAILLAMP HOUSING PANEL O/S	11	520.50	\$700.00	—
1PC	REAR BUZZLE SENSOR	11		\$98.00	X
1PC	REAR FENDER O/S	Dis/magat	1193.20	\$1,483.00	—
1PC	REAR FENDER OUTER PROTECTOR O/S	Dis	380.20	\$760.00	—
1PC	REAR FENDER INNER TRIM BOARD O/S	Dis	421.20	\$790.00	—
1PC	REAR FENDER UNDER INNER CLOTH O/S	Dis	293.50	\$388.20	—
1PC	REAR FLOOR PANEL	11		\$1,280.00	X
1PC	REAR FLOOR INNER SIDE PANEL O/S	Bent/11		\$450.00	—
1PC	REAR FLOOR PANEL	Tools Sponge	441.20	\$522.00	—
1PC	REAR EXHAUST	11		\$765.00	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$108.00	X
1PC	REAR WHEEL HUB BEARING O/S	11		\$485.00	X
1PC	REAR AXLE BEAM ASSY	11		\$1,899.00	X
1PC	REAR SHOCK ABSORBER O/S	11		\$288.00	X
				\$18,918.90	
				LESS 20%	\$15,135.12

S.NETT

1PC	REAR WINDSCREEN SEALANT	11	\$50.00	X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00	X
1PC	REAR END PANEL SEALANT	21	\$50.00	✓
1SET	REAR BUMPER REVERSE SENSOR	511	\$680.00	X
1PC	REAR SPORT RIM O/S	611	\$950.00	600
1SET	REAR FLOOR PANEL INSULATOR	11	\$120.00	X

TO CEHCK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	30
TO DISMANTLE & REFX REAR WINDSCREEN	11	\$150.00 X
TO TRANSFER TAILGATE MECHANISM	11	\$100.00 X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00 80
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM		\$180.00 60
TO DISMANTLE & REFIX REAR EXHAUST	11	\$100.00 X
TO SPRAY RUST PROOFING		\$100.00 80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	1400
TO PUTTY & SPRAY PAINTING	\$1,500.00	1100
TOTAL	\$21,215.12	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

p- 6680  
202  
5344.00  
650  
2770  
8764  
202  
7011.20