

IMPERIUM AUTOMOTIVE
25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800
HP : 9748 9940 Shawn Tan
Email : shawn7530@hotmail.com

not Authorised
near
29/11/24
2/5 \$ 2100/
3 days. Live ph. After repair

22 NOVEMBER 2024

Vehicle No: SNM6387K

Model : KIA NIRO

QTY	List Items	AMOUNT
1	Front Bumper <i>de/To, n</i>	<i>\$44.20</i> \$1221.40 ✓
1	Front Bumper Lower Lid <i>cut/To, n</i>	<i>650.00</i> \$940.50 ✓
1	Front Bumper Side Retainers <i>su</i>	\$60.30 X
1	Front Headlamps <i>u u</i>	\$1784.50 X
1	Front Fender (L) <i>R</i>	\$680.40 X
1	Front Fender Inner Shield (L) <i>u u</i>	\$155.20 X
1	Front Fender Wheel Arch Garnish (L) <i>cut</i>	<i>415.00</i> \$488.30 ✓
1	Front Wheel Rim <i>1</i>	\$1350.40 X
1	Front Wheel Bearings <i>u u</i>	\$363.00 X
1	Front Knuckle Arms <i>u u</i>	\$589.70 X
		\$7633.70
Less 10%		\$763.37
		\$6870.33

Special Nett Items

1	Front Bumper Clip (1 set) <i>net</i>	\$60.00 <i>30</i>
1	Front Fender Inner Shield Clip (1 set) <i>u u</i>	\$60.00 X
1	Front Tyre <i>su</i>	\$300.00 X
		\$420.00

Labour Charges

To Remove, Refit Front Undercarriage	<i>u u</i>	\$500.00 X
To Conduct wheel alignment	<i>u u</i>	\$180.00 X
To Apply undercoating	<i>u u</i>	\$120.00 X
Panel Beating		\$1000.00 <i>300</i>
To Re-Spray Painting on the affected areas		\$1200.00 <i>580</i>
		\$3000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Grand Total \$10,290.33

P-1910.2
102
1719.18
30
880