

IMPERIUM AUTOMOTIVE
25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800
HP : 9748 9940 Shawn Tan
Email : shawn7530@hotmail.com

not Authorised
29/11/24
2/6 @ 2300/
3 days. After repair

22 NOVEMBER 2024

Vehicle No: SNM6387K

Model : KIA NIRO

QTY	List Items	AMOUNT
1	Front Bumper lower lip cut/Torn	\$1221.40
1	Front Bumper cut/Torn	\$940.50
1	Front Bumper Side Retainers su	\$60.30 X
1	Front Headlamps n	\$1784.50 X
1	Front Fender (L) R	\$680.40 X
1	Front Fender Inner Shield (L) n	\$155.20 X
1	Front Fender Wheel Arch Garnish (L) cut	\$488.30
1	Front Wheel Rim 1	\$1350.40
1	Front Wheel Bearings n	\$363.00 X
1	Front Knuckle Arms n	\$589.70 X
		\$7633.70
Less 10%		\$763.37
		\$6870.33

Special Nett Items

1	Front Bumper Clip (1 set) n	\$60.00 30 s/w
1	Front Fender Inner Shield Clip (1 set) n	\$60.00 X
1	Front Tyre su	\$300.00 X
		\$420.00

Labour Charges

To Remove, Refit Front Undercarriage	n	\$500.00 X
To Conduct wheel alignment	n	\$180.00 X
To Apply undercoating	n	\$120.00 X
Panel Beating		\$1000.00 300
To Re-Spray Painting on the affected areas		\$1200.00 500
		\$3000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Grand Total

\$10,290.33

Acknowledged by Repairer

Signature:

Date:

P-2262.40
102
2036.16
30
P80