

ONE GARAGE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT
SINGAPORE 415875
TEL: 96311088

TO	: NTUC	DATE	2/12/2024
VEHICLE NO	: SMV6587P (2020)		
VEHICLE MODEL	: HONDA VEZEL		Xiao Chen
CHASSIS NO	: RU11327389		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 38.50	\$ 77.00
2	REAR BUMPER <i>Dented</i>	1	\$ 880.00	\$ 880.00
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 23.50	\$ 47.00
4	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 141.10	\$ 282.20
5	REAR SIDE BUMPER <i>new</i>	2	\$ 195.00	\$ 390.00
6	REAR END PANEL <i>Dented</i>	1	\$ 585.00	\$ 585.00
7	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 98.40	\$ 98.40
8	TAILLAMP <i>lt</i>	2	\$ 474.60	\$ 949.20
9	TAILLAMP PANEL <i>3 new</i>	2	\$ 135.50	\$ 271.00
10	TAILLAMP PANEL INNER <i>new</i>	2	\$ 221.60	\$ 443.20
11	TAILGATE <i>Distorted</i>	1	\$ 1,100.00	\$ 1,100.00
12	TAILGATE LOCK <i>Damaged</i>	1	\$ 182.50	\$ 182.50
13	TAILGATE LOCK STRIKER <i>new</i>	1	\$ 24.70	\$ 24.70
14	TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 189.10	\$ 189.10
15	TAILGATE LAMP <i>RH out, LH cracked</i>	2	\$ 413.20	\$ 826.40
16	TAILGATE LAMP RUBBER GASKET <i>new</i>	2	\$ 38.50	\$ 77.00
17	TAILGATE HINGE <i>new</i>	2	\$ 58.00	\$ 116.00
18	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 325.00	\$ 325.00
19	TAILGATE INNER TRIM BOARD <i>cracked</i>	1	\$ 285.60	\$ 285.60
20	TAILGATE BUZZER SENSOR <i>new</i>	1	\$ 85.20	\$ 85.20
21	TAILGATE ANTENNA SENSOR <i>new</i>	1	\$ 60.10	\$ 60.10
22	TAILGATE OPENER SWITCH SENSOR <i>new</i>	1	\$ 125.50	\$ 125.50
23	TAILGATE INNER PULL POCKET <i>cracked</i>	1	\$ 35.90	\$ 35.90
24	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 120.00	\$ 120.00
25	HONDA LOGO <i>new</i>	1	\$ 30.40	\$ 30.40
26	VEZEL EMBLEM <i>new</i>	1	\$ 45.90	\$ 45.90
27	REAR FENDER INNER TRIM BOARD <i>new</i>	2	\$ 305.20	\$ 710.40
28	REAR EXHAUST PIPE <i>new</i>	1	\$ 598.60	\$ 598.60
29	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 28.50	\$ 28.50
30	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 48.30	\$ 48.30
31	REAR EXHAUST PIPE HEAT SHIELD <i>new</i>	1	\$ 98.30	\$ 98.30
32	SPARE TYRE PANEL <i>new</i>	1	\$ 1,130.00	\$ 1,130.00
33	SPARE TYRE PANEL TOP COVER <i>new</i>	1	\$ 306.60	\$ 306.60
34	SPARE TYRE PANEL TOOLS TRAY SPONGE <i>new</i>	1	\$ 285.40	\$ 285.40
35	SPARE TYRE PANEL UNDERCOVER <i>new</i>	1	\$ 225.10	\$ 225.10
36	SPARE TYRE SIDE PANEL <i>new</i>	1	\$ 178.00	\$ 178.00
37	SPARE TYRE UNDER JACK PANEL <i>new</i>	1	\$ 138.00	\$ 138.00

TOTAL PRICE: \$ 11,399.50

4875.50

3900.40

LESS 20% \$ 2,279.90
SUB TOTAL PRICE: \$ 9,119.60

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>new</i>	1	\$ 30.00	\$ 30.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 280.00	\$ 280.00
4	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
5	TAILGATE OUTER GARNISH CLIPS (SET) <i>new</i>	1	\$ 25.00	\$ 25.00
6	TAILGATE INNER TRIM BOARD CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
8	SPARE TYRE PANEL UNDERCOVER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
9	SPARE TYRE PANEL INSULATION PAD	1	\$ 250.00	\$ 250.00
10	REAR FENDER INNER TRIM BOARD CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
11	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00
12	VIDEO RECORDER	1	\$ 600.00	\$ 600.00
TOTAL :				\$ 1,865.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	<i>700</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>600</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
5	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
6	TO REMOVE VIDEO RECORDER	\$ 100.00	<i>50</i>	
7	TO REMOVE UPHOLSTERY AND REAR SEAT	\$ 380.00	<i>60</i>	
8	TO SPRAY TUFF COAT	\$ 150.00	<i>60</i>	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	<i>60</i>	
10	TO TRANSFER TAILGATE GLASS	\$ 180.00	<i>120</i>	
11	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	<i>X</i>	
TOTAL		\$ 4,360.00		

ESTIMATE REPORT

TOTAL PARTS COST: \$ 10,984.60
TOTAL LABOUR COST: \$ 4,360.00
TOTAL REPAIR COST: \$ 15,344.60

total: 6000.40
4/8: 4.8K ✓
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: