



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110418/Enp3m4
16 RAFFLES QUAY	Date:	03/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9521D	Veh. Inspected	SLV 4034T
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24010164MFCT	Excess	\$0.00
Assign From	CHRIS LIM	Assign Date	19/11/2024

2. Vehicle Details

Make & Model	TOYOTA C-HR	C.C	1797
Engine No.	2ZR8163450	Year of Reg.	28/12/2017
Chassis No.	ZYX102062447	Colour	SILVER
Odometer	97159 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/50R18	YOKOHAMA	5
L/H Front Tyre	225/50R18	YOKOHAMA	5
R/H Rear Tyre	225/50R18	YOKOHAMA	5
L/H Rear Tyre	225/50R18	YOKOHAMA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/11/2024	Inspection Date	20/11/2024
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days