



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	Mr V Viknesh 416 Tampines Street 41 #08-345 Singapore 520416 Mobile: 91111111				
		Document No. 0					
		Document Date 19/11/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZYX10		28/12/2017	SLV4034T	0	34858	72/DS/SLV4034T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
ZYX102062447		2ZR8163450	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP INS:FIRST CAPITAL INSURANCE TP VEH:SHA9521D DATE OF ACC:18.11.2024				50	100.00
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				/	198.00
3	B	BP-LAB2 CHECK WIRING SYSTEM				/	134.64
4	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				?	792.00
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				/	198.00
6	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR				/	198.00
7	B	BP-MECH2 REPLACE REAR EXHAUST PIPE SYSTEM				/	792.00
8	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				792	3960.00
9	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				656	3280.00
10	1	T52159-10300 B0 COVER, RR BUMPER	1.00	2298.00			2298.00
11	2	T52453-10901 GUARD, RR BUMPER,	1.00	573.60			573.60
12	3	T52162-10010 PLATE, RR BUMPER,	1.00	24.60			24.60
13	4	T75392-35200 RETAINER, OUTSIDE	6.00	5.60			33.60
14	5	T52023-10040 REINFORCEMENT	1.00	512.40			512.40
15	6	T52576-10010 RETAINER, RR BUMPER	1.00	155.60			155.60
16	7	T52563-10010 RETAINER, RR BUMPER,	1.00	78.90			78.90
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary			Total	
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others			Less Amount Due	

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mr V Viknesh 416 Tampines Street 41 #08-345 Singapore 520416 Mobile: 91111111
	Document No. 0	
	Document Date 19/11/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZYX10		28/12/2017	SLV4034T	0	34858	72/DS/SLV4034T

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
ZYX102062447	2ZR8163450	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
17	8	T52164-10010 PLATE, RR BUMPER, LH	1.00	126.10		126.10
18	9	T81920-10031 REFLECTOR ASSY, X	1.00	83.40		83.40
19	0	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
20	1	T81481-10050 BRACKET, FOG LAMP	1.00	110.60		110.60
21	2	T58307-10361 PANEL SUB-ASSY, BODY	1.00	1092.40		1092.40
22	3	T58399-10020 COVER, FLOOR UNDER, ?	1.00	262.10		262.10
23	4	T58327-10061 INSULATOR, MAIN ?	1.00	201.00		201.00
24	5	T64716-10090 C1 COVER, DECK TRIM, RR ?	1.00	352.20		352.20
25	6	T89348-F4120 RETAINER, ULTRASONIC	2.00	21.50		43.00
26	7	T52462-10010 PAD, RR BUMPER, RH	1.00	18.20		18.20
27	8	T89348-F4140 C0 RETAINER, ULTRASONIC	2.00	28.30		56.60
28	9	T89341-F4020 C1 SENSOR, ULTRASONIC, CUT	1.00	503.90		503.90
29	0	T17430-37680 PIPE ASSY, EXHAUST	1.00	2624.80		2624.80

Steve (LKK)
20/11/24, 12.30 pm

PIP, by Bel sky, 4 days

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	18,861.64
	Please acknowledge receipt of vehicle	Parts 9,209.00 Labour 9,652.64 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00%	1,697.55
			Less	0.00
			Amount Due	20,559.19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Customer Copy