

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

ECICS LIMITED

10 EUNOS ROAD 8
#09-04A SINGAPORE POST CENTRE
SINGAPORE 408600

Tel: 63374779

Fax: 63389267

Attn: Motor Claim Department

Your Ref No: TP 1124-8364

Claim Type: Third Party

Accident Date: 18 November 2024

TP Veh Reg No: GBK9369X

Estimate No: **EST1512050**

Date: 19 Nov 2024

Policy No: M

Veh Reg No: SLS8533J

Make/Model: MAZDA MAZDA5

WAGON 2.0 AT EU6

Chassis No: JM6CW1071H0126500

Engine No: PE10525207

Reg. Date: 09 Oct 2017

not Authorised
for
repair
20/11/24
2/5 #5800/
whenever they
6 days

Estimate Repair Cost to Vehicle No: SLS8533J

Description	Unit Cost	Quantity	Cost SGD	Amount SGD
Spare Parts				
1 FRONT BUMPER <i>cut/De</i>	380.00	1 PC	380.00 ✓	
2 FRONT BUMPER SIDE RETAINER - LH <i>we</i>	18.00	1 PC	18.00 ✓	
3 FRONT BUMPER CLIPS <i>re</i>	2.80	10 PC	28.00 ✓	
4 FRONT BUMPER FOGLAMP COVER - LH <i>ny</i>	35.00	1 PC	35.00 X	
5 HEADLAMP UNIT - LH <i>re</i>	650.00	1 PC	650.00 ✓	
6 HEADLAMP LOWER RETAINER - LH <i>ny</i>	20.00	1 PC	20.00 X	
7 FRONT FENDER - LH <i>cut/But</i>	150.00	1 PC	150.00 ✓	
8 FRONT FENDER COWLING - LH <i>re</i>	95.00	1 PC	95.00 ✓	
9 FRONT FENDER COWLING CLIPS - LH <i>re</i>	2.80	10 PC	28.00 ✓	
10 FRONT RIM - LH <i>cut</i>	550.00	1 PC	550.00 ✓	
11 FRONT DOOR - LH <i>cut/But</i>	650.00	1 PC	650.00 ✓	
12 FRONT DOOR STICKER - LH <i>re</i>	110.00	1 PC	110.00 ✓	
13 FRONT DOOR WEATHERSTRIP - LH <i>ny</i>	38.00	1 PC	38.00 X	
14 FRONT DOOR TOP HINGE - LH <i>ny</i>	25.00	1 PC	25.00 X	
15 FRONT DOOR LOWER HINGE - LH <i>ny</i>	20.00	1 PC	20.00 X	
16 FRONT DOOR CHECKER - LH <i>ny</i>	40.00	1 PC	40.00 X	
17 FRONT DOOR OUTER CHANNEL MOULDING - LH <i>ny</i>	65.00	1 PC	65.00 ✓	
18 FRONT DOOR GLASS - LH <i>cut</i>	150.00	1 PC	150.00 ✓	
19 SIDE MIRROR ASSY - LH <i>re</i>	150.00	1 PC	150.00 ✓	
20 SIDE MIRROR OUT COVER - LH <i>re</i>	55.00	1 PC	55.00 ✓	
21 REAR DOOR - LH <i>ny</i>	580.00	1 PC	580.00 X	
22 REAR DOOR STICKER - LH <i>ny</i>	110.00	1 PC	110.00 X	
23 REAR DOOR WEATHERSTRIP - LH <i>ny</i>	85.00	1 PC	85.00 X	
24 ROCKER PANEL OUTER GARNISH - LH <i>ny</i>	455.00	1 PC	455.00 X	
25 REAR FENDER - LH <i>cut/But</i>	850.00	1 PC	850.00 ✓	
26 REAR BUMPER - LH <i>cut/But</i>	450.00	1 PC	450.00 ✓	
27 REAR BUMPER SIDE RETAINER - LH <i>ny</i>	18.00	1 PC	18.00 X	
28 REAR BUMPER CLIPS <i>ny</i>	2.80	10 PC	28.00 X	
			5,833.00	
Add 10%			583.30	6,416.30
Labour				
29 TO KNOCK OUT DENTS, CUT/WELD REAR FENDER, REMOVE, REPLACE ACCIDENT PORTIONS- <i>220</i>	1,760.00	1 JOB	1,760.00 <i>990</i>	
30 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	1,600.00	1 JOB	1,600.00 <i>1200</i>	
31 TO CHECK WIRING-	30.00	1 JOB	30.00 ✓	
32 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	150.00 <i>60</i>	
33 ANTI RUST- <i>1 desr</i>	90.00	1 JOB	90.00 <i>50</i>	
34 TO TRANSFER 2 DOOR FITTINGS-	160.00	1 JOB	160.00 <i>60</i>	
35 TO 4 WHEEL ALIGNMENT-	75.00	1 JOB	75.00 <i>60</i>	
36 TO REMOVE, REPLACE RIM & TYRE BALANCING-	45.00	1 JOB	45.00 <i>11</i>	3,910.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

Total	10,326.30
Add GST @ 9%	929.37
Total Amount Payable SGD	11,255.67

SINGAPORE DOLLAR ELEVEN THOUSAND TWO HUNDRED FIFTY FIVE AND CENTS SIXTY SEVEN ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4379
102
481690
2485
72665
5813

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE