

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

25/6/2024

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson
Singapore 079914

Vehicle No: SKT8910K
Vehicle Model: H/CITY
Est No: CBMQ24060208
Claims ref:
Accident Date: 25/06/24
In Charge: KEONG
Remarks:

No	Description	Qty	U. Price	Amounts S\$
2	TO SPRAY AFFECTED AREAS, REAR BOOT, REAR END PANEL, REAR FENDER L+R, SPARE TYRE PANEL, REAR BUMPER, REAR REVERSE SENSOR, AND AFFECTED AREAS			\$ 850.00 400
3	TO REMOVE & REFIX LUGGAGE COMPARTMENT SIDE GARNISH SIDE TRIM BOARD & OTHER ATTACHMENT PARTS			\$ 80.00 40?
4	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE			\$ 60.00 40
5	TO RUST PROOF AFFECTED AREAS			\$ 50.00 30
TOTAL LABOUR COST S\$				\$ 1,880.00 910

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

AMOUNT S\$ \$ 5,463.24
GST @ 9% \$ 491.69
AMOUNT DUE S\$ \$ 5,954.93

3702.20
740.44
2961.76
35.00 SN
910.00 LB
3906.76

LS \$3100/-

4 days

Rashu
Hp 90010068

4 days

L/S

19/07/24

Rashu after repair

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

25/6/2024

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson
Singapore 079914

Vehicle No: SKT8910K
Vehicle Model: H/CITY
Est No: CBMQ24060208
Claims ref:
Accident Date: 25/06/24
In Charge: KEONG
Remarks:

No	Description	Qty	U. Price	Amounts S\$
----	-------------	-----	----------	-------------

LIST ITEMS:

1	REAR BOOT <i>St</i>	1	PC \$ 965.50	\$ 965.50 ✓
2	REAR BOOT LOGO <i>neu</i>	1	PC \$ 64.30	\$ 64.30 ✓
3	REAR BOOT EMBLEM "CITY" <i>neu</i>	1	PC \$ 71.20	\$ 71.20 ✓
4	REAR BOOT MOULDING <i>scr</i>	1	PC \$ 155.20	\$ 155.20 ✓
5	REAR BOOT LOCK <i>X</i>	1	PC \$ 160.10	\$ 160.10 X
6	REAR BOOT RUBBER <i>neu</i>	1	PC \$ 117.60	\$ 117.60 ✓
7	REAR BOOT LAMP RH <i>cm</i>	1	PC \$ 279.50	\$ 279.50 ✓
8	REAR PANEL ?	1	PC \$ 476.40	\$ 476.40 ✓
9	REAR PANEL TRIM <i>X</i>	1	PC \$ 112.30	\$ 112.30 X
10	REAR LAMP RH ?	1	PC \$ 395.20	\$ 395.20 ✓
11	REAR BUMPER <i>de</i>	1	PC \$ 786.40	\$ 786.40 ✓
12	REAR BUMPER BRACKET L+R (1pc) <i>RH neu</i>	2	PC \$ 55.20 ✓	\$ 110.40
13	REAR BUMPER CLIPS <i>neu</i>	10	PC \$ 3.90	\$ 39.00 ✓
14	REAR BUMPER REFLECTOR RH <i>X</i>	1	PC \$ 96.30	\$ 96.30 X
15	REAR BUMPER SENSOR <i>scr</i> (1pc)	1	PC \$ 296.70 ✓	\$ 593.40

LIST TOTAL S\$

\$ 4,422.80

20% DISCOUNT S\$

\$ (884.56)

\$ 3,538.24

SPECIAL NET ITEMS:

1	REAR NUMBER PLATE <i>cm</i>	1	PC \$ 45.00	\$ 45.00 35
---	-----------------------------	---	-------------	------------------------

SPECIAL NET TOTAL S\$

\$ 45.00

LABOUR CHARGE: ?

1	TO CUT & WELD REAR END PANEL, TO REPAIR REAR LAMP PANEL, REAR SPARE TYRE PANEL, TO REMOVE & REFIX DAMAGED PARTS STRAIGHTEN & REALIGN AFFECTED AREAS			
---	---	--	--	--

\$ ~~840.00~~ 400