# **LKK Auto Consultants** #01-25 Paya Ubi Industrial Park, 51 **Ubi Avenue 1** 408933

**Insurer Reference: SNM24D205311** 

Repairer Reference: 074191

**Registration: GU456A** Date calculated: 04/12/2024 4:29 PM Printed: 04/12/2024 4:29 PM

### **Summary Information**

Claim

Location: Work Provider: Singapore (SG) China Taiping Insurance

(Singapore) Pte Ltd

**Full Report** 

Printed by: Claim Reference: KK LAU

SNM24D205311

Currency: Date of Incident: SGD 19/09/24

Estimated Repair Time: Actual Repair Days:

Hire Car Start: Hire Car End:

#### **Vehicle Details**

Vehicle

NISSAN Manufacturer: Model: NV200 (M20) Sub Model: **BASE MODEL** Model Sheet Number: 71 89 01

Registration: GU456A

VIN number: JN1YAAM20Z0001296

Odometer: **Model Specs** 

HEATED DOOR MIRRORS FULL WHEEL COVERS PRODUCTION JAPAN COMBI

PREPARE OFF VEHICLE **BASECOAT CLEAR** 


### **Vehicle Condition**

#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

### **Damage Areas**

All	
Underbody	



# **Tyres Condition**

Tyre Brand Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Outer),

 $mm \hspace{1cm} mm \hspace{1cm} mm \hspace{1cm} mm \hspace{1cm} mm \hspace{1cm} Middle), \hspace{1cm} mm$ 

Spare Tyre Brand

Tread (Spare), mm

#### Labour

	Time Base 10 WU/h	Price = 42.	00 SGD/h
Code	Description	WU	Price SGD
NO NUMBER	JOB ALLOWANCE	5.0	21.00
UE10A1	RENEW L/F WING INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE, BUMPER MOULDINGS, WHEELHOUSE LINER, HEADLAMP AND NECESSARY ATTACHED PARTS	18.0	75.60
UA10A1)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	4.0	16.80
WH40A1	ADJUST HEADLAMPS	3.0	12.60
UH40A1)	R + R L/F DOOR TRIM	2.0	8.40
UJ10A1)	R + R LEFT MIRROR	1.0	4.20

	Total of Labour				138.60
Paint					
Paint Work	SYSTEM A	AZT	Tim	ne Basis	10 WU/h
Code	Description - BASECOAT CLEAR			WU	Price SGD
	L/F WING NEW PART PAINTING			10.0	
Paint Materia	l Per Part				
Code	Description				Price SGD
0741	L/F WING NEW PART PAINTING				21.67
	<b>Labour Cost - Paint</b> Factor	42.00 SGD/h	Hrs	wu	Price SGD
	Time Paint	.2.00 000,		10.0	
	Preparation Main Work Metal <b>Total</b>	10 WU/h	2.50 3.50	25.0 35.0	105.00 147.00
	Material Cost - Paint				Price SGD
	New Part Painting Material-constant Metal Preparation				21.67 28.60
	Total				50.27

## **Spare Parts**

Spare Farts				
Code	Description	Part Number	Part Source	prices as at 2015-06-01/01 Price SGD
0281	FRONT BUMPER	62022 JX00A	Original	400.00
0741	L/F WING	63101 JX00A	Original	350.00
1737	L/DOOR MIRROR	96302 JX06E	Original	280.00
7211	L/F WHEEL COVER	40315 JX00A	Original	130.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Addition(+10.00%)			0.00 1,160.00 116.00
	Total			1,276.00

**Labour Cost** 

**Panel / Mechanical Labour** 

WU

33.0

138.60

Hrs

3.30

# **Final Calculation**

	SGD	SGD
Parts	1,160.00	
Addition(+10.00%)	116.00	
Total Parts		1,276.00
Labour Time Base 10 WU/h		
Total 33.0 WU X 42.00 SGD/h	138.60	
Total of Labour		138.60
Paint Work Time Base 10 WU/h		
Labour Cost 35.0 WU X 42.00 SGD/h	147.00	
Material Cost	50.27	
Total Paint Including Material		197.27
Repair Cost Excludes GST		1,611.87
GST (+9.00%)		145.07
Repair Cost Included GST		1,756.94
Deductions (Excludes GST)		
Repair Cost Discount (+20.00%)	-322.37	
Total Of Deductions (Excludes GST)		-322.37
Grand Total Excludes GST		1,289.50
GST (+9.00%)		116.06
Grand Total Included GST		1,405.56

#### Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

### **Assessment Note**

Author	Date	Text
LKKAUTO	04/12/2024 4:27 PM	Lump Sum \$1,300.00
dingauto	03/12/2024 3:41 PM	Finalize Report
dingauto	20/11/2024 4:08 PM	Assessment.1