LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

INV No.: SAC2401664

INV Date: 05-12-2024

Reference CS/SMR24110425/Knp3m4

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SLN 6921L Insured Veh. SHB 1023Y

Claim No. TAX/11/24/2061

Policy No.

Accident Date 19/11/2024 Inspection Date 20/11/2024

Description	Amount
Survey Inspection	128.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	le Des Experts En	Automobile
MS	STRIDES PREMIER	AUTOMOTIVE SERVICES PL.	Ref:	CS/SMR24110425/Knp3m4
	60 WOODLANDS IN 757705	IDUSTRIAL PARK E4 SINGAPORE	Date:	05/12/2024
	757705		Code:	SMR
1.		Policy Particulars :- T	HIRD PARTY CLA	IM
	Insured Veh.	SHB 1023Y	Veh. Inspected	SLN 6921L
	Policy No.	-	Coverage	0
	Claim No.	TAX/11/24/2061	Excess	\$0.00
	Assign From	HUA YEN	Assign Date	20/11/2024
2.		Vehicle	Details	
	Make & Model	TOYOTA AQUA (A)	C.C	1496
	Engine No.	1NZR501404	Year of Reg.	15/05/2017
	Chassis No.	NHP106585450	Colour	WHITE
	Odometer	118648 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL	•	
3.		Conditions	of Tyres	
		Size	Make	Balance (mm)
	R/H Front Tyre	185/60R15	GREENTRAC	7
	L/H Front Tyre	185/60R15	GREENTRAC	7
	R/H Rear Tyre	185/60R15	REAC	8
	L/H Rear Tyre	185/60R15	REAC	8
4.		Description of	of Damages	
THE	VEHICLE SUSTAIN	ED DAMAGES AT THE REAR AND FRO	ONT PORTION.	
DAM	AGES SEE DETAILS	6.		
5.		General In	formation	
	Accident Date	19/11/2024	Inspection Date	20/11/2024
	Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2 #01-05 AMK AUTOPOINT SINGAPORE 568047	2A	
5a.		Rema	arks	
		AS CONDUCTED ON A"WITHOUT PRE YOUR INSTRUCTIONS, WE HAVE NO		REPAIRS.
5b.		Estimate Day	s of Repair	
		-		

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLN 6921L

	REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR TAILGATE	BENT	\$980.00	\$980.00	
1	REAR TAILGATE "AQUA" EMBLEM	NECESSARY	\$80.00	\$80.00	
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	\$80.00	\$80.00	
1	REAR TAILGATE TOYOTA EMBLEM	NECESSARY	\$80.00	\$80.00	
1	REAR TAILGATE LOCK	DENTED	\$220.00	\$220.00	
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	\$285.00	\$0.00	
1	REAR TAILGATE GARNISH COVER	CRACKED	\$130.00	\$130.00	
2	REAR TAILGATE NUMBER PLATE LAMP @\$60.00	CRACKED	\$120.00	\$120.00	
1	REAR TAILGATE CAMERA	DENTED	\$200.00	\$200.00	
1	REAR TAILGATE INNER TRIM	SERVICEABLE	\$170.00	\$0.00	
1	REAR WIPER ARM ASSEMBLY	DENTED	\$150.00	\$150.00	
1	REAR WIPER MOTOR	JAMMED/CRACKED	\$580.00	\$580.00	
1	REAR TAIL LAMP LH	SERVICEABLE	\$530.00	\$0.00	
1	REAR TAIL LAMP RH	SERVICEABLE	\$530.00	\$0.00	
1	REAR TAIL LAMP BRACKET LH	SERVICEABLE	\$75.00	\$0.00	
1	REAR TAIL LAMP BRACKET RH	SERVICEABLE	\$75.00	\$0.00	
1	REAR BUMPER	BUCKLED	\$848.00	\$848.00	
1	REAR BUMPER REINFORCEMENT	BUCKLED	\$590.00	\$590.00	
1	REAR BUMPER SMART BUZZER	CRACKED	\$80.00	\$80.00	
1	REAR BUMPER SIDE BRACKET LH	BENT	\$86.00	\$86.00	
1	REAR BUMPER SIDE BRACKET RH	BENT	\$86.00	\$86.00	
1	REAR BUMPER UNDER COVER	CRACKED	\$221.00	\$221.00	
1	REAR EXHAUST	TO REPAIR SEE LABOUR	\$718.00	\$0.00	
1	REAR END PANEL	BENT	\$556.00	\$556.00	
1	REAR END PANEL UPPER COVER	MTG CRACKED	\$118.00	\$118.00	
1	REAR FLOOR PANEL TOP BOARD	SERVICEABLE	\$250.00	\$0.00	
1	FRONT BONNET	BENT	\$1,084.00	\$1,084.00	
1	FRONT BUMPER	BUCKLED	\$924.00	\$924.00	
1	FRONT BUMPER TOYOTA EMBLEM	NECESSARY	\$88.50	\$88.50	
1	FRONT BUMPER REINFORCEMENT	BENT	\$450.00	\$450.00	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	FR ONT BUMPER ABSORBER FOAM	SERVICEABLE	\$105.00	\$0.00		
1	FRONT GRILLE ASSEMBLY	CRACKED	\$390.40	\$390.40		
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	\$805.00	\$0.00		
	LESS 25.00% DISCOUNT		(\$2,921.23)	(\$2,035.48)		
			\$8,763.67	\$6,106.42		

	Special Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$100.00	\$40.00		
1	REAR TAILGATE INNER TRIM CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00		
1	REAR BUMPER REVERSE SENSOR (SN)	MISSING	\$300.00	\$200.00		
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00		
1	REAR NUMBER PLATE & HOLDER (SN)	DENTED	\$50.00	\$45.00		
1	REAR END PANEL JOINT SEALANT (SN)	NECESSARY	\$120.00	\$30.00		
1	REAR END PANEL UPPER COVER CLIPS (SN)	NECESSARY	\$40.00	\$40.00		
1	FRONT NUMBER PLATE & HOLDER (SN)	DENTED	\$50.00	\$45.00		
1	FRONT BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00		
			\$810.00	\$500.00		

Labo	our		
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL		\$500.00	\$400.00
LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST REAR ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF REAR EXHAUST		\$1,000.00	\$600.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, FRONT BONNET, FRONT BUMPER & ETC		\$1,200.00	\$1,000.00
LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS		\$120.00	\$60.00
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC		\$120.00	\$50.00
LABOUR CHARGES TO REMOVE & REPLACE REAR EXHAUST & ETC	NOT NECESSARY	\$300.00	\$0.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Labo	our		
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
TO CHECK WIRING & ELECTRICAL SYSTEM		\$120.00	\$40.00
		\$3,360.00	\$2,150.00
GRAND TOTAL		\$12,933.67	\$8,756.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$7,000.00
Report Ref No: CS/SM	R24110425/Knp3m4		

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

SO0324BJ0001 / OPTIMA WERKZ PTE LTD ENTRY DATE & TIME: 19/11/2024 13:24 (SGT) SUBMITTED BY: EE YING YI VERSION: 1 (19/11/2024 13:24 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission

Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

19/11/2024 13:24 (SGT)

Actual Driver

19/11/2024 08:20 (SGT)

Singapore

BKE TOWARDS PIE BEFORE EXIT 3

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLN6921L

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No.

Alternative Phone No.

Yes

OPTIMA WERKZ PTE.LTD.

2XXXXX455W

JANET.ONG@OCLEASING.SG

(Phone) +65-91719288

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Vehicle Fuel

First Regisration Date

Chassis no

Effective Date/Time of Ownership

Aqua

Toyota

Private hire

No - Claiming third party

Private car

Auto

1496

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

India International Insurance Pte Ltd

DRIVER



D23MFL0007412 01

Name of Driver NRIC No. Date Of Birth Occupation Driving Pass Date **Driving License Pass Class Driving License Validity** Driving experience Gender Mobile Number Alt. Phone Number Email Address

Address Address complement

Postcode

Is the driver the policyholder? If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Chain Collision Raining Wet

LI ZI'EN, BENJAMIN

(Phone) +65-81018803

BENJAMIN.LI.1988@GMAIL.COM

BLK 118 WOODLANDS AVENUE 5

SXXXX364H

03/10/1988

26/11/2010

14 YEARS

Indoor

Valid

Male

#10-39

739019

No

No

No

Yes

Yes

No

No

3

Hirer

3

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police? Police Station Name Police Station Phone No Alt, Police Station Phone No Police Station Address Was notice of intended Prosecution given? If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFET TO POLICE REPORTNO: T/20241119/7040

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Yes Yes

Yes

Traffic Police

(Phone) +65-65470000 (Fax) +65-65474900

10 Ubi Avenue 3 Singapore 408865

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB1023Y

Vehicle Manufacturer MG Vehicle Model

Vehicle Variant Vehicle Colour Green

Vehicle Category Taxi Name of Driver NG CHAN HOCK NRIC No SXXXX404I

Contact Number (Phone) +65-96930751 Address BLK 174 YISHUN AVENUE 7

Address complement #11-847 Postcode 760174

Insurance Company Name Nature Of Damage

Details of property damaged in accident No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBE7301K

Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour

Vehicle Category Goods vehicle

Name of Driver APPARAJ AATHAVAN

Passport No/FIN GXXXX223M

Contact Number (Phone) +65-83814794

Address

Address complement Postcode Insurance Company Name Nature Of Damage

Details of property damaged in accident No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person LI ZI'EN, BENJAMIN

Gender Phone No (Phone) +65-81018803

Address **BLK 118 WOODLANDS AVENUE 5**

Address Complement #10-39 Post Code 739019

Approximate Age Years Old Injuries Sustained

Injured person in which vehicle? SLN6921L Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes

e / Date &

Policyholder's Signat Time

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre

Sketch Plan

+ GBE 7301 K SLN 6921L > SHRIDZIY

BKE towards PIE before Exit 3

ke fer	to	report	the Accident : 1/202411	19/7040		
	-					
					1.9	
						u.Ö
			HAVE 14 DAYS FRO			

Declaration

We declare the foregoing particulars are true in every respect

A CALLAD A C

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



T/20241119/7040

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3 Report No. T/20241119/7040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/11/2024 11:55		de:	Vide Report No.:	Station Diary No.:
Informan	's Particular	8		
	Informant: BENJAMIN		Address: 118 WOODLANDS AVENUE	5 #10-39 SINGAPORE 739019
ID Type / NRIC NO	ID No.: / \$8838364	IH.	Contact No.: Home/Office:	Mobile: 81018803
Nationalit SINGAPO	y: DRE CITIZE	N	Email: BENJAMIN.LI.1988@GMAIL.G	СОМ
Sex: Male	Age: 36	Date of Birth: 03/10/1988	Type of Informant: Vehicle Owner	
Race: Chinese			Language: English	
Occupation: Intellectual property manager		nanager	Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/11/2024 08:20	Type of Location Straight Road
Location: BANGKIT ROAD		Road Surface:		
A CONTRACTOR OF THE PARTY OF TH				
		Wet		
Weather: Raining Traffic Flow: One Way			Tra Hea	fic Volume:

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
GBE7301K	Lorry					0
SHB1023Y	Taxi	MG		Green		0
SLN6921L	Motor car	TOYOTA	aqua	White	Seriously Damaged	0

Details of Person Involved		
Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



T/20241119/7040

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20241119/7040

CONTINUATION OF REPORT

Name	LI ZI'EN, BENJAMIN		ID No.		S8838364H
Related Vehicle	SLN6921L (Motor car)		Contact No.		81018803
Hospital/Clinic	NEO CLINIC & SURGERY		Class of Driving Licence & Expiry Date		Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	19/11/2024	Date Disch	Discharge NIL		
No. of Days granted Medical Leave (MC) 03		Degree of I	Degree of Injury		

Brief Details.

At about 08:19 on 19 November 2024, I was driving my car (SLN6921L) on the center lane of BKE towards PIE before exit 3 (4KM mark) when a Green Strides Premier Taxi (SHB1023Y) rear ended my car. During the impact, my car was pushed forward and I made contact with a lorry from Plasterceil Specialist Pte Ltd (GBE7301K). Road condition was wet, and traffic was heavy but slow moving.

We took photos and exchanged particulars with everyone. Aetos officers were on scene to direct traffic but left after we were escorted to the side of the expressway.



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



3 of 3 Report No. T/20241119/7040

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.			
Signature Of Interpreter: Not applicable	Date/Time: 19/11/2024 11:55			
Officer In Charge Of Case: TP / AEIT / PHNG KAR SOON Contact No.: 65476439	Classification Of Case:			
NP168				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 1 of 8)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 2 of 8)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 3 of 8)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 4 of 8)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 5 of 8)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 6 of 8)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 7 of 8)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

o: 19960/198R GST I 19-9607198-R **INSPECTION PHOTOS (Page 8 of 8)**







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 1 of 5)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 2 of 5)












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 3 of 5)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 4 of 5)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 5 of 5)









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)







