

ASS. REC. BY:

REF:

SMR/

CS/SMR 24110425/knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

3/12 11 Amp & 7000k. Cables (Red. \$ 5933.68, 45%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

7

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Veh No:

SLN 69212 Yr Regn: 05.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy A909 C.C. 1498

Colour

White A/C: Insured / Std / NI / NA

Sp. Reading

118648 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NHP106 585450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

Continental 185/60R15
R: ReacBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

19/11/24

D.O.I.

20/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

455W

Vehicle Details

Vehicle No.:

SLN6921L

Vehicle to be Exported:

No

Intended Deregistration Date:

19 Nov 2024

Vehicle Make:

TOYOTA

Vehicle Model:

AQUA HYBRID 1.5S CVT

Primary Colour:

White

Manufacturing Year:

2017

Engine No.:

1NZR501404

Chassis No.:

NHP106585450

Maximum Power Output:

73.0 kW (97 bhp)

Open Market Value:

\$20,847.00

Original Registration Date:

15 May 2017

First Registration Date:

15 May 2017

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

14 May 2027

PARF Rebate Amount:

\$3,000.00

Intended COE Rebate Details

COE Expiry Date:

14 May 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,789.00

COE Rebate Amount:

\$12,620.00

Total Rebate Amount:

\$15,620.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 19 Nov 2024

OK

Date: 19/11/2024
Vehicle No: SLN6921L
Model: TOYOTA AQUA HYBRID 1.5S CVT
Chassis: NHP106585450-2017
Reg.Year: 2017

Third Party Insurer: MS FIRST CAP
Third Party Veh No: SHB1023Y
Date of Accident: 19/11/2024
Estimator: TING AN
Surveyor:

*Not with the
11 Rm & 7000h
Kunoy After Rain
7 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		By \$980.00
2	REAR TAILGATE "AQUA" EMBLEM	1		Re \$80.00
3	REAR TAILGATE "HYBRID" EMBLEM	1		Re \$80.00
4	REAR TAILGATE TOYOTA EMBLEM	1		Re \$80.00
5	REAR TAILGATE LOCK	1		Re \$220.00
6	REAR TAILGATE WEATHERSTRIP	1		Re \$285.00
7	REAR TAILGATE GARNISH COVER	1		CM \$130.00
8	REAR TAILGATE NUMER PLATE LAMP	2	\$60.00	CM \$120.00
9	REAR TAILGATE CAMERA	1		Re \$200.00
10	REAR TAILGATE INNER TRIM	1		Re \$170.00
11	REAR WIPER ARM ASSEMBLY	1		Re \$150.00
12	REAR WIPER MOTOR	1		Re \$580.00
13	REAR TAIL LAMP LH	1		Re \$530.00
14	REAR TAIL LAMP RH	1		Re \$530.00
15	REAR TAIL LAMP BRACKET LH	1		Re \$75.00
16	REAR TAIL LAMP BRACKET RH	1		Re \$75.00
17	REAR BUMPER	1		Re \$848.00
18	REAR BUMPER REINFORCEMENT	1		Re \$590.00
19	REAR BUMPER SMART BUZZER	1		CM \$80.00
20	REAR BUMPER SIDE BRACKET LH	1		Re \$86.00
21	REAR BUMPER SIDE BRACKET RH	1		Re \$86.00
22	REAR BUMPER UNDER COVER	1		CM \$221.00
23	REAR EXHAUST	1		Re \$718.00
24	REAR END PANEL	1		Re \$556.00
25	REAR END PANEL UPPER COVER	1		Re \$118.00
26	REAR FLOOR PANEL TOP BOARD	1		Re \$250.00
27	FRONT BONNET	1		Re \$1,084.00
28	FRONT BUMPER	1		Re \$924.00
29	FRONT BUMPER TOYOTA EMBLEM	1		Re \$88.50
30	FRONT BUMPER REINFORCEMENT	1		Re \$450.00
31	FRONT BUMPER ABSORBER FOAM	1		Re \$105.00
32	FRONT GRILLE ASSEMBLY	1		CM \$390.40
33	FRONT SUPPORT PANEL	1		Re \$805.00

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19/11/2024
Vehicle No: SLN6921L
Model: TOYOTA AQUA HYBRID 1.5S CVT
Chassis: NHP106585450-2017
Reg.Year: 2017

Third Party Insurer: MS FIRST CAP
Third Party Veh No: SHB1023Y
Date of Accident: 19/11/2024
Estimator: TING AN
Surveyor:

SUB TOTAL	\$11,684.90
LESS 25%	-\$2,921.23
PARTS TOTAL	\$8,763.68

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		Re \$100.00
2	REAR TAILGATE INNER TRIM CLIPS	1		nn \$50.00
3	REAR BUMPER REVERSE SENSOR	1		my \$300.00
4	REAR BUMPER CLIPS	1		Re \$50.00
5	REAR NUMBER PLATE & HOLDER	1		De \$50.00
6	REAR END PANEL JOINT SEALANT	1		Re \$120.00
7	REAR END PANEL UPPER COVER CLIPS	1		Re \$40.00
8	FRONT NUMBER PLATE & HOLDER	1		De \$50.00
9	FRONT BUMPER CLIPS	1		Re \$50.00
S/N TOTAL				\$810.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

400/ \$500.00

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$1,000.00 600/

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, FRONT BONNET, FRONT BUMPER & ETC.

1000/ \$1,200.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

60/ \$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 50/

LABOUR CHARGES TO REMOVE & REPLACE REAR EXHAUST & ETC.

nn \$300.00 X

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19/11/2024
Vehicle No: SLN6921L
Model: TOYOTA AQUA HYBRID 1.5S CVT
Chassis: NHP106585450-2017
Reg.Year: 2017

Third Party Insurer: MS FIRST CAP
Third Party Veh No: SHB1023Y
Date of Accident: 19/11/2024
Estimator: TING AN
Surveyor:

TO CHECK WIRING & ELECTRICAL SYSTEM.

40/ \$120.00

LABOUR TOTAL \$3,360.00

TING AN

TOTAL \$12,933.68

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 156143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

