

Date: 19/11/2024
Vehicle No: SLN6921L
Model: TOYOTA AQUA HYBRID 1.5S CVT
Chassis: NHP106585450-2017
Reg.Year: 2017

Third Party Insurer: MS FIRST CAP
Third Party Veh No: SHB1023Y
Date of Accident: 19/11/2024
Estimator: TING AN
Surveyor:

*Not Withheld
1 Ramp & 700ch
Recovery After Pain 7 'lass*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR TAILGATE	1		By \$980.00	✓
2	REAR TAILGATE "AQUA" EMBLEM	1		Na \$80.00	✓
3	REAR TAILGATE "HYBRID" EMBLEM	1		Na \$80.00	✓
4	REAR TAILGATE TOYOTA EMBLEM	1		Na \$80.00	✓
5	REAR TAILGATE LOCK	1		Na \$220.00	✓
6	REAR TAILGATE WEATHERSTRIP	1		Pa \$285.00	X
7	REAR TAILGATE GARNISH COVER	1		CMT \$130.00	✓
8	REAR TAILGATE NUMER PLATE LAMP	2	\$60.00	CMT \$120.00	✓
9	REAR TAILGATE CAMERA	1		Red \$200.00	✓
10	REAR TAILGATE INNER TRIM	1		Se \$170.00	X
11	REAR WIPER ARM ASSEMBLY	1		Na \$150.00	✓
12	REAR WIPER MOTOR	1		Im/CMT \$580.00	✓
13	REAR TAIL LAMP LH	1		Pa \$530.00	X
14	REAR TAIL LAMP RH	1		Pa \$530.00	X
15	REAR TAIL LAMP BRACKET LH	1		Pa \$75.00	Z
16	REAR TAIL LAMP BRACKET RH	1		Pa \$75.00	Z
17	REAR BUMPER	1		Pa \$848.00	✓
18	REAR BUMPER REINFORCEMENT	1		Pa \$590.00	✓
19	REAR BUMPER SMART BUZZER	1		CMT \$80.00	✓
20	REAR BUMPER SIDE BRACKET LH	1		By \$86.00	✓
21	REAR BUMPER SIDE BRACKET RH	1		By \$86.00	✓
22	REAR BUMPER UNDER COVER	1		CMT \$221.00	✓
23	REAR EXHAUST	1		Pa \$718.00	X
24	REAR END PANEL	1		By \$556.00	✓
25	REAR END PANEL UPPER COVER	1		Na/CMT \$118.00	✓
26	REAR FLOOR PANEL TOP BOARD	1		Pa \$250.00	X
27	FRONT BONNET	1		By \$1,084.00	✓
28	FRONT BUMPER	1		Pa \$924.00	✓
29	FRONT BUMPER TOYOTA EMBLEM	1		Na \$88.50	✓
30	FRONT BUMPER REINFORCEMENT	1		By \$450.00	✓
31	FRONT BUMPER ABSORBER FOAM	1		Pa \$105.00	X
32	FRONT GRILLE ASSEMBLY	1		CMT \$390.40	✓
33	FRONT SUPPORT PANEL	1		Pa \$805.00	X

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19/11/2024
 Vehicle No: SLN6921L
 Model: TOYOTA AQUA HYBRID 1.5S CVT
 Chassis: NHP106585450-2017
 Reg.Year: 2017

Third Party Insurer: MS FIRST CAP
 Third Party Veh No: SHB1023Y
 Date of Accident: 19/11/2024
 Estimator: TING AN
 Surveyor:

SUB TOTAL	\$11,684.90
LESS 25%	-\$2,921.23
PARTS TOTAL	\$8,763.68

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>na</i> \$100.00
2	REAR TAILGATE INNER TRIM CLIPS	1		<i>na</i> \$50.00
3	REAR BUMPER REVERSE SENSOR	1		<i>mis</i> \$300.00
4	REAR BUMPER CLIPS	1		<i>na</i> \$50.00
5	REAR NUMBER PLATE & HOLDER	1		<i>DU</i> \$50.00
6	REAR END PANEL JOINT SEALANT	1		<i>na</i> \$120.00
7	REAR END PANEL UPPER COVER CLIPS	1		<i>na</i> \$40.00
8	FRONT NUMBER PLATE & HOLDER	1		<i>DU</i> \$50.00
9	FRONT BUMPER CLIPS	1		<i>na</i> \$50.00
S/N TOTAL				\$810.00

400n
X
200n
✓
450n
300n
✓
450n
✓

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

400
 \$500.00

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

600
 \$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, FRONT BONNET, FRONT BUMPER & ETC.

1000
 \$1,200.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

60
 \$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

50
 \$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR EXHAUST & ETC.

na \$300.00 *X*

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19/11/2024
 Vehicle No: SLN6921L
 Model: TOYOTA AQUA HYBRID 1.5S CVT
 Chassis: NHP106585450-2017
 Reg.Year: 2017

Third Party Insurer: MS FIRST CAP
 Third Party Veh No: SHB1023Y
 Date of Accident: 19/11/2024
 Estimator: TING AN
 Surveyor:

TO CHECK WIRING & ELECTRICAL SYSTEM.

401
\$120.00

LABOUR TOTAL \$3,360.00

TING AN TOTAL \$12,933.68

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

