



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 9006Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FR LWR BUMPER GRILLE	CRACKED	95.00	95.00
1	FRONT BUMPER	CRACKED	300.00	300.00
1	FRONT BUMPER CLIPS	NECESSARY	12.00	12.00
1	FRONT DRIVING CAMERA	SERVICEABLE	350.00	-
1	FRONT SPOILER	CRACKED	55.00	55.00
1	FRT BUMPER ABSORBER	CRACKED	65.00	65.00
1	FRT BUMPER SUPPORT	TO REPAIR SEE LABOUR	250.00	-
1	FRT LWR BUMPER MLDG	DENTED	35.00	35.00
1	FRT NO PLATE BRKT	BENT	15.00	15.00
1	L/F BUMPER COVER	DENTED	45.00	45.00
1	L/F INNER SENSOR	MISSING	130.00	130.00
1	L/F OUT PARK AID SEN	SERVICEABLE	90.00	-
1	PARK SENSOR(3)	SERVICEABLE	90.00	-
1	R/F INNER SENSOR	SERVICEABLE	130.00	-
1	R/F OUT PARK AID SEN	SERVICEABLE	90.00	-
1	RADIATOR	SERVICEABLE	350.00	-
1	SENSOR(4)	SERVICEABLE	90.00	-
1	UP/CVR RADIAT GRILLE	CRACKED	110.00	110.00
			2,302.00	862.00
<u>SPECIAL NETT ITEMS</u>				
1	GRILLE (SN)	DENTED	330.00	130.00
1	SUNDRY (SN)	NECESSARY	100.00	100.00
1	FRT NO.PLATE (SN)	MISSING	35.00	35.00
			465.00	265.00
<u>LABOUR</u>				
TOTAL 66.0 WU X 42.00 SGD/H. INCLUSIVE OF THE REPAIR OF FRT BUMPER SUPPORT.			277.20	277.20
FIXED RATE.			250.00	250.00
LABOUR COST 69.0 WU X 42.00 SGD/H.			289.80	247.80

Report Ref No. CS/CTI24110426/Kqh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	MATERIAL COST.		135.80	135.44
			952.80	910.44
	GRAND TOTAL		3,719.80	2,037.44
RECOMMENDED COST OF REPAIRS				2,037.44
LESS EXCESS				-500.00
NETT LIABILITY				1,537.44

Report Ref No. CS/CT124110426/Kqh3m4(N)

MARKET VALUE: \$68,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$40,197.00=NETT VALUE: \$27,803.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.