

REF:

ASSIGNMENT

Front: _____ Date: _____

Estn: ~~Est~~OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MVTo In ~~Vehicle~~ No: _____at ~~W/O~~ ~~W/O~~ m/s _____

of _____

Insured: _____

Policy: ~~File~~Claims: ~~No~~

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

N/S	O/S

Remarks: Tlevah had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW162SR Yr Regn: 2020 / NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienna Hybrid C.D. 1496Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 246766 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NHP1707194650Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

King Boss

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 25/11/24.

Survey held at

MG SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

COE Expiry: _____

Estimate given during: Yes (✓)
1st Survey: No ()MV: 911CPV: 35.5KNett: 55.5K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee: _____

Transportation: _____

3 + RS. \$1

Photos

Others

Report Format: _____

Report Date / Time / File / No

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	22-11-24
CLAIM TYPE:	T/P CLAIM
TO:	FIRST CAPITAL
VEHICLE DETAILS	
VEHICLE NO:	SMW1625R
MAKE & MODEL:	TOYOTA SIENTA HYBRID 1.5
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	17 November, 2024
TIME:	0100HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR SLIDING DOOR RH <i>Dented</i>	1	\$ 1,588.60	\$ 1,588.60 ✓
2	REAR SLIDING DOR OUTER GARNISH <i>Dented</i>	1	\$ 320.00	\$ 320.00 ✓
3	REAR FEDNER RH <i>Peris</i>	1	\$ 1,120.50	\$ 1,120.50 +
4	REAR FENDER OUTER GARNISH <i>hit</i>	1	\$ 160.00	\$ 160.00 ✓

TOTAL PRICE \$ 3,189.10

LESS 25% \$ 797.28

SUB TOTAL PRICE \$ 2,391.83

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR OUTER GARNISH CLIPS(SET) <i>2 per</i>	1	\$ 20.00	\$ 20.00 ✓
2	REAR FENDER OUTER GARNISH CLIPS(SET)	1	\$ 20.00	\$ 20.00 10

TOTAL \$ 40.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,200.00	\$ 1,200.00 3w
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,200.00	\$ 1,200.00 4w
3	TUFF COAT	1	\$ 200.00	\$ 200.00 30
4	WIRING CHECK	1	\$ 100.00	\$ 100.00 +

5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00
6	REMOVE AND REFIX REAR DOOR MECHANISH	1	\$ 120.00	\$ 120.00

TOTAL \$ 3,100.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	2,431.83
TOTAL LABOUR COST	\$	3,100.00
TOTAL REPAIR COST	\$	5,531.83

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adrian Lj
2/5 25/11/24.
03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: