



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060287/Anh3
16 RAFFLES QUAY	Date:	22/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMB 1532K	Veh. Inspected	SND 53K
Policy No.	D-24102356MFBP	Coverage	0
Claim No.	D24005659MFBP	Excess	\$0.00
Assign From	JOANNE TAN	Assign Date	27/06/2024

2. Vehicle Details

Make & Model	BMW 528i	C.C	1997
Engine No.	A3700078N20B20A	Year of Reg.	16/02/2012
Chassis No.	WBAXG320X0C593774	Colour	GREY
Odometer	282567 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/35R20	PIRELLI	6
L/H Front Tyre	255/35R20	PIRELLI	6
R/H Rear Tyre	255/35R20	PIRELLI	6
L/H Rear Tyre	255/35R20	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/06/2024	Inspection Date	26/06/2024
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days