

ASS. REC. BY:

REF:

F021

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: £105k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNG 9758K Yr Regn: 09, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttle C.C. 1898Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 218961 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GPT 2207586Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Annate

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 16/11/24 D.O.I. 2/12/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/12 212pm @ 3150h Coler

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Not Authored
1/1/2018 @ 3150h
Pricing After Paim
4 days

Vehicle Number : SNG 9758K

Date: 16.11.24

S/N Parts Description

- 1 Rear tailgate
- 2 Rear tailgate Shuttle emblem
- 3 Rear tailgate Hybrid emblem
- 4 Rear tailgate emblem
- 5 Rear tailgate outer garnish
- 6 Rear tailgate lock
- 7 Rear tailgate rubber
- 8 Rear tailgate inner board
- 9 Rear tailgate windscreen mldg
- 9 Rear bumper
- 10 Rear bumper retainer X 2
- 11 Rear bumper inner bracket LH
- 12 Rear bumper reflector X 2
- 13 Rear bumper chrome mldg
- 14 Taillamp LH & RH
- 15 Rear end panel
- 16 Rear end panel top garnish

Unit Price Amt

Pr	\$1,295.00	✓
na	\$95.00	—
na	\$96.00	—
na	\$68.00	X
ln	\$286.20	X
nd	\$299.00	—
Ad/di	\$186.00	✓
ln	\$350.40	X
na	\$121.60	✓
Bu	\$936.00	✓
\$42.50	ln	\$85.00 X
	n	\$132.00 X
\$76.80	ln	\$153.60 X
	nd	\$126.90 ✓
\$592.30	ln	\$1,184.60 X
	R	\$681.00 X
	ln	\$155.80 X

Special Nett

- 1 Rear bumper clips
- 2 Rear No. plate
- 3 Rear windscreen sealant
- 4 Rear bumper reverse sensor

na	\$50.00	✓
ln	\$60.00	X
na	\$80.00	40ln
ln	\$300.00	X

Labour

- 1 To remove and refit damaged parts, cut/weld damaged areas. \$1000.00 500l
- 2 To spray paint on affected areas. \$1,000.00 600l
- 3 To remove and refit rear windscreen \$200.00 120l
- 4 To remove and refit reverse sensor \$100.00 50l
- 5 Check wiring \$50.00 15l
- 6 Tuff coating \$120.00 30l

\$2,470.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: